



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

IMMEDIATE ADVICE

To : AXA Insurance Pte Ltd

DATE: 22/12/20

Survey details

Date of loss	21/12/2020
Date of appointment	21/12/2020
Date of survey	21/12/2020
Location of survey	GARAGE 13 PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SGK 5088Z
Make and Model	TOYOTA HARRIER 2.4
Date of registration	25/9/2006
Excess	
Market Value	\$14,000.00
Part Rebate	\$3,777.00
Nett Loss	\$10,223.00

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	2 days (est)

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$1,000.00-\$2,000.00