



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

21/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Ergo
Veron.

Accident date: 18/12/2020

Estimated repair cost for vehicle no: PC4699C TOYOTA HIACE VAN TURBO 3.0 M '16

CHASSIS: JTFHT02P400189375

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Boot Lid <i>Distorted</i>		\$1,712.45
2	2	Rear Boot Lid Hinge <i>HE m</i>	\$171.70	\$343.40
3	2	Rear Boot Lid Shock Absorber <i>HE m</i>	\$374.45	\$748.90
4	1	Rear Boot Lid Toyota Hiace Sticker <i>HE</i>		\$57.60
5	1	Rear Boot Lid Emblem Logo <i>m</i>		\$41.10
6	1	Rear Boot Lid Centre Moulding <i>Distorted</i>		\$281.90
7	2	Rear Boot Lid Number Plate Lamp <i>HE m</i>	\$67.80	\$135.60
8	1	Rear Boot Lid Inner Lock <i>Distorted</i>		\$374.25
9	1	Rear Boot Lid Inner Power Lock <i>Distorted</i>		\$276.20
10	1	Rear Boot Lid Inner Aluminium Panel (Special Nett) <i>HE m</i>		\$1,000.00
11	1	Rear Boot Lid Inner Trim Board <i>Torn</i>		\$372.50
12	1	Rear Boot Lid Weatherstrip <i>HE</i>		\$381.90
13	1	Rear Boot Lid Windscreen <i>HE</i>		\$1,355.00
14	1	Rear Boot Lid Windscreen Seal <i>HE</i>		\$105.00
15	2	Rear Tail Lamp <i>Distorted</i>	\$371.50	\$743.00
16	2	Rear Tail Lamp Panel <i>Regis</i>	\$355.80	\$711.60
17	2	Rear Tail Lamp Lower Cover <i>Distorted</i>	\$182.10	\$364.20
18	2	Rear Tail Lamp Lower Cover Retainer <i>HE m</i>	\$171.45	\$342.90
19	4	Rear Tail Lamp Clip <i>m</i>	\$8.00	\$32.00
20	2	Rear Fender Air Duct <i>HE m</i>	\$172.45	\$344.90
21	1	Rear Bumper <i>Distorted</i>		\$374.45
22	10	Rear Bumper Clip <i>m</i>	\$6.50	\$65.00
23	2	Rear Bumper Side Retainer <i>m</i>	\$131.35	\$262.70
24	1	Rear End Panel Outer <i>Distorted</i>		\$581.10
25	1	Rear End Panel Inner <i>Distorted</i>		\$591.25
26	1	Rear Floor Panel <i>Regis</i>		\$1,850.00
27	1	Rear Floor Panel Top Moulding <i>Distorted</i>		\$174.10
28	8	Rear Floor Panel Top Moulding Clip <i>HE m</i>	\$6.50	\$52.00

29	1	Rear Floor Panel Carpet <i>3 new</i>	\$750.00	+
30	1	Rear Floor Panel Plywood <i>3 new</i>	\$550.00	+
31	1	Rear Spare Tyre Bracket <i>new</i>	\$172.10	+
32	1	Rear Exhaust <i>3 new</i>	\$1,712.85	+
33	1	Rear Centre Exhaust <i>3 new</i>	\$1,829.10	+
34	1	Rear Center Seat Cushion & Leather <i>3 new</i>	\$700.00	+
35	1	Rear L/H Seat Cushion & Leather <i>3 new</i>	\$700.00	+

7174.5
5380.50

Subtotal :- \$20,089.05

S/n	Qty	Items / Special Nett	U/price	Amount
36	1	Rear Boot Lid 70km/H Sticker <i>new</i>		\$20.00 <i>10</i>
37	1	Rear Boot Lid Number Plate <i>Best</i>		\$50.00 <i>25</i>
38	1	Rear Boot Lid Reverse Camera <i>Damaged</i>		\$680.00 <i>400</i>
39	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$350.00 <i>200</i>

635

Subtotal :- \$1,100.00

Labour charges

To remove & refit trimboard and cushion	\$800.00 <i>80</i>
To remove & refit reverse sensor	\$100.00 <i>50</i>
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 <i>30</i>
Tuff kote	\$150.00 <i>80</i>
Panel beating	\$2,000.00 <i>1000</i>
Spray painting	\$2,000.00 <i>800</i>

2220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Subtotal :- \$4,520.00

Total:- \$25,709.05

total: 8235.50
4/8: 6.6K
7 Days

6.6K