

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 18 Jan 2021

Preliminary Advice

Insured Vehicle No	: SMH6861X		
TP Vehicle No	: SMQ4104P	Accident Date	: 18/12/2020
Make	: MAZDA BIANTE	Assignment Date	: 21/12/2020
Date of Inspection	: 22/12/2020	Est. Duration of Repair	: 10
Inspection At	: SM AUTOMOTIVE - KAKI BUKIT (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,222.26
Revised Amount	:S\$	15,900.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,900.12
Lump Sum Repair	:S\$	12,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.