

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

18/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPMS26.

Denise.

Accident date: 18/12/2020

Estimated repair cost for vehicle no: SMQ4104P MAZDA BIANTE 5-DOOR 2.0L 17'

CHASSIS: JM6CC1071H0110727

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$1,118.40 <i>+</i>
2	2	Front Bonnet Hinge <i>new</i>		\$0.00 <i>+</i>
3	1	Front Bonnet Lock <i>new</i>		\$221.70 <i>+</i>
4	1	Front Bonnet Insulation <i>new</i>		\$129.10 <i>+</i>
5	10	Front Bonnet Insulation Clip <i>new</i>	\$6.50	\$65.00 <i>+</i>
6	1	Front Bonnet Inner Rubber		\$65.70 <i>+</i>
7	2	Front Head Lamp <i>new</i>	\$2,744.40	\$5,488.80 <i>2</i>
8	2	Front Head Lamp Lower Bracket <i>new</i>	\$133.50	\$267.00 <i>+</i>
9	2	Front Side Lamp <i>new</i>	\$678.45	\$1,356.90 <i>+</i>
10	1	Front Bumper <i>new</i>		\$1,074.30 <i>+</i>
11	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>+</i>
12	2	Front Bumper Side Retainer <i>new</i>	\$40.80	\$81.60 <i>+</i>
13	1	Front Bumper Reinforcement <i>new</i>		\$701.10 <i>+</i>
14	1	Front Bumper Center Lower Garnish <i>new</i>		\$128.50 <i>+</i>
15	2	Front Bumper Fog Lamp <i>new</i>	\$463.70	\$927.40 <i>+</i>
16	2	Front Bumper Fog Lamp Cover <i>new</i>	\$186.10	\$372.20 <i>+</i>
17	1	Front Grille Assy <i>new</i>		<u>\$2,237.96</u> <i>2131</i>
18	10	Front Grille Clips <i>new</i>	\$6.50	\$65.00 <i>20</i>
19	1	Front Grille Emblem Logo <i>new</i>		\$73.40 <i>+</i>
20	2	Front Fender <i>new</i>	\$382.20	\$764.40 <i>+</i>
21	2	Front Fender Cowling <i>new</i>	\$181.10	\$362.20 <i>+</i>
22	10	Front Fender Cowling Clip <i>new</i>	\$6.50	\$65.00 <i>+</i>
23	1	Front Support Panel <i>new</i>		\$486.30 <i>+</i>
24	2	Front Support Panel Lock <i>new</i>	\$38.60	\$77.20 <i>+</i>
25	1	Front Air-Con Condenser <i>new</i>		\$1,821.80 <i>+</i>
26	1	Front Radiator <i>new</i>		\$1,008.20 <i>+</i>
27	1	Front Radiator Fan Motor Assy <i>new</i>		\$1,262.00 <i>+</i>
28	1	Rear Boot Lid <i>Dented</i>		\$1,699.70 <i>+</i>

29	2	Rear Boot Lid Hinge <i>new</i>	\$35.90	\$71.80	+
30	2	Rear Boot Lid Shock Absorber <i>new</i>	\$164.10	\$328.20	+
31	1	Rear Boot Lid Skyactive Logo <i>new</i>		\$117.70	✓
32	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$218.30	✓
33	1	Rear Boot Lid Number Plate <i>Best</i>		\$50.00	✓
34	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$57.70	\$115.40	+
35	1	Rear Boot Lid Inner Lock <i>Jammed</i>		\$246.40	✓
36	1	Rear Boot Lid Inner Trim Board <i>zinc</i>		\$426.30	✓
37	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00	50
38	1	Rear Boot Lid Center Lamp <i>new</i>		\$2,018.60	+
39	1	Rear Boot Lid Center Chrome <i>new</i>		\$290.10	+
40	1	Rear Boot Lid Reverse Camera <i>new</i>		\$680.00	+
41	2	Rear Tail Lamp <i>new</i>	\$1,117.20	\$2,234.40	+
42	4	Rear Tail Lamp Clip <i>3pc</i>	\$6.50	\$26.00	+
43	2	Rear Tail Lamp Panel <i>new</i>	\$397.50	\$795.00	+
44	1	Rear Bumper <i>Delaid</i>		\$1,170.20	✓
45	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	50
46	1	Rear Bumper Reverse Sensor (Special Nett) <i>new</i>		\$380.00	200/50
47	2	Rear Bumper Side Retainer <i>new</i>	\$48.80	\$97.60	✓
48	2	Rear Bumper Side Reflector <i>new</i>	\$124.80	\$249.60	+
49	1	Rear Bumper Lower Center Chrome <i>new</i>		\$130.10	✓
50	2	Rear Bumper Lower Side Chrome <i>new</i>	\$86.00	\$172.00	✓
51	1	Rear End Panel <i>Delaid</i>		\$303.20	✓
52	1	Rear End Panel Top Garnish <i>Delaid</i>		\$122.30	✓
53	2	Rear Fender Inner Trim Board <i>new</i>	\$632.70	\$1,265.40	+
54	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00	+
55	1	Rear Spare Tyre Panel <i>new</i>		\$1,852.20	+
56	1	Rear Spare Tyre Panel Top Cover <i>new</i>		\$775.20	+
57	1	Rear Exhaust <i>Not new</i>		\$1,109.80	+
58	1	Rear Center Exhaust <i>Not new</i>		\$1,439.60	+

14577.5
11662
S.N: 200.

Subtotal :- \$38,892.26

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00	+
To remove & refit rear reverse camera	\$120.00	50
To remove & refit rear exhaust	\$280.00	+

To remove & refit cushion & trim board

~~\$380.00~~ 80

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To check wiring

~~\$100.00~~ 60

Towing fee

\$150.00 X

Tuff kote

~~\$150.00~~ 60

Panel beating

~~\$3,500.00~~ 1400

Spray painting

~~\$3,000.00~~ 1300

Subtotal :- \$8,330.00

Total:- \$47,222.26

22/12/20

102yr

Supplementary: 868.12.

total: 15600.12

L/s: 12.41K.

12.71K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

22/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 20/12/2020

SMQ4104P Mazda Bionte.

Supplementary repair cost for vehicle no: SMF9951K NISSAN QASHQAI 1.2 A '18

CHASSIS: SJNFEAJ11U2393165

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Support Lock Panel <i>new</i>		\$238.45 +
2	1	Front L/H Lower Support Garnish Guard <i>cancel</i>		\$82.25 ✓
3	2	Front Grille Lower Chrome <i>cancel</i>	\$187.45	\$374.90 ✓
4	1	Rear Boot Lid Sound Proof Insulation <i>new</i>		\$600.00 3w/sv
5	1	Rear End Panel Antenna Sensor Assy <i>cancel</i>		\$320.00 ✓
Total:-				\$1,615.60 253

22/12/20

10 Days.

710.15

568.12

SIN: 3w.

Supplementary: 868.12