

*	TO SUPPLY FRONT BUMPER CLIPS <i>SVC</i>	\$ 50.00 X 30/-
*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS <i>HH</i>	\$ 50.00 X
*	TO SUPPLY 1PC TYRE <i>50% depreciation HH</i>	\$ 300.00 120/- X
*	TO SUPPLY 1PC SPORT RIM <i>HH</i>	\$ 1,400.00 X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,200.00 200/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,200.00 200/-

	TO TUFF COAT DAMAGED AREAS	\$ 300.00	74
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00	74
*	TO CONDUCT COMPUTERIZED ALIGNMENT TEST	\$ 120.00	64
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	74

LABOUR & S/N TOTAL: \$ 5,220.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 9,846.90

982.78

1/5 750/-

21/12/2020 @ 1800 hrs

H/A Andrew

1/2 hr 2 days.

Yan

LKK Auto

Check part prices.

Check damage consistency.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: