

COMFORTDELGRO

REPAIR ESTIMATE*

VEHICLE NO SHD7142L

DATE 07/12/20 12:00 AM

MAKE :

CHIANG/PCAP

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		de✓	\$1,052.20
10	BUMPER CLIP		un✓	\$22.00
1	FRONT FENDER LH		ht✓	\$663.00
1	HEAD LAMP LH		unb✓	\$1,800.00
1	HEAD LAMP SUPPORT PANEL		X	\$907.40
1	FRONT BUMPER BRACKET TOP LH/		X	\$44.80
1	FRONT BUMPER BRACKET SIDE /LH		X	\$49.20
1	FRONT BUMPER GRILLEH/LH		X	\$187.20
SUB TOTAL				\$4,725.80
20.00%				\$945.16
				\$3,780.64
Labour Charge				
Panel Beating				420 \$600.00
Spray painting				400 \$500.00
Check lighting				30 \$50.00
Adjust wheel alignment				850 \$90.00
				\$1,240.00
ESTIMATE TOTAL				\$5,020.64
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Waste
Tanglin 97445749
WP' 2 (3 days)
21/12/20 01pm
Resurvey after repair
tanglin@khand.com