



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ANDREW YAP MING HWE Reg No/Reg Date SMW2051P / 09/11/202 Date In/Mileage / 0 Chassis No MMBSTA13AMH000618 Engine No 3A92UJP3584 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/12/2020/ 12:34		442 / CocoLu	61000			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								20.00
Sundry								3150.00
E PNT88000								3600
RENEW FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL, FRT DOOR RH					450 x 8			100.00
REAR DOOR RH, REPAIR REAR FENDER RH, REAR BUMPER, SIDE SILL RH								80.00
E PNT88000								120.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								30.00
A 54900099								50.00
TOP UP AIRCON GAS								3150.00
A 54900099								180.00
CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								180.00
A 54900099								120.00
CHECK WIRING & ELECTRICAL SYSTEM								450.00
M SUNDRY								30.00
SUPPLY FRT NUMBER PLATE WITH FRAME								360.00
E PNT98000								541.31
FPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL					350 x 8			69.30
FRT DOOR RH, REAR DOOR RH, SIDE SILL RH, REAR FENDER RH, REAR BUMPER								6.16
E PNT88000								
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								
B WHEELALIGNMENT								
To Conduct Computerize Full Wheel Alignment								
A 54900099								
RENEW FRT UNDER CARRIAGE								
M SUNDRY								
TRANSFER NEW RIM								
M SUNDRY								
APPLY FRT RIGHT TYRE					1.00	703.00	23.00	
M FACE,FR BUMPER					1.00	90.00	23.00	
M GRILLE,FR UNDER					1.00	8.00	23.00	
M BRACKET,FR BUMPER SIDE,RH								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



E & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ANDREW YAP MING HWEE Reg No/Reg Date SMW2051P / 09/11/202 Date In/Mileage / 0 Chassis No MMBSTA13AMH000618 Engine No 3A92UJP3584 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/12/2020/ 12:34		442 / CocoLu	61000			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GARNISH,FR BUMPER,RH	CUT			1.00	44.00	23.00	33.88
M	AIR DAM,SIDE,FR RH (Black)	CUT			1.00	19.00	23.00	14.63
M	GRILLE ASSY,RADIATOR	CUT			1.00	597.00	23.00	459.69
M	MARK,THREE-DIA	N/C			1.00	53.00	23.00	40.81
M	COVER,FR BUMPER	MIS (Tru covr)			1.00	12.00	23.00	9.24
M	COVER,FR BUMPER GRILLE	CRU (Top cover)			1.00	157.00	23.00	120.89
M	GARNISH,FR BUMPER SIDE	(chrome upper)	CUT		1.00	168.00	23.00	129.36
M	GARNISH,FR BUMPER SIDE	(" lower)	CUT		1.00	120.00	23.00	92.40
M	FENDER,FR RH	DD			1.00	428.00	23.00	329.56
M	SHIELD,FR WHEELHOUSE,RH	DD			1.00	98.00	23.00	75.46
M	PANEL ASSY,FR END	(chrome)	TN		1.00	918.00	23.00	706.86
M	PANEL ASSY,FR DOOR,RH	N/C			1.00	996.00	23.00	766.92
M	HINGE,FR DOOR,LWR RH	X NM			1.00	54.00	23.00	41.58
M	HINGE,FR DOOR,UPR RH	X NM			1.00	54.00	23.00	41.58
M	PANEL ASSY,RR DOOR,RH	DD			1.00	831.00	23.00	639.87
M	GARNISH,FR PILLAR,RH	X NM			1.00	30.00	23.00	23.10
M	AIR DAM,SIDE,RH	(side str)	CUT		1.00	189.00	23.00	145.53
M	TAPE,FR DOOR SASH,RH	N/C			1.00	29.00	23.00	22.33
M	TAPE,RR DOOR SASH,RH	dec			1.00	29.00	23.00	22.33
M	MIRROR ASSY,DOOR,RH	CUT			1.00	638.00	23.00	491.26
M	HEADLAMP ASSY,RH	BR			1.00	1697.00	23.00	1306.69
M	LAMP ASSY,FOG,FR LH	X NM			1.00	303.00	23.00	233.31
M	TANK,WINDSHIELD WASHER	CRU			1.00	74.00	23.00	56.98
M	MOTOR,WINDSHIELD WASHER(*)	? X NM			1.00	139.00	23.00	107.03
M	SHAFT AS,FR AXLE DRIVE,RH	? X NM			1.00	1201.00	23.00	924.77
M	HUB ASSY,FR WHEEL	X NM			1.00	240.00	23.00	184.80
M	BEARING,FR WHEEL HUB	X NM			1.00	121.00	23.00	93.17
M	KNUCKLE,RH	(CRU)	CUT		1.00	365.00	23.00	281.05
M	WHEEL,DISC	? X NM	Bent		1.00	598.00	23.00	460.46
M	ARM ASSY,FR SUSP,LWR RH	? X NM			1.00	278.00	23.00	214.06
M	CROSSMEMBER,FR AXLE,NO.1	BT			1.00	864.00	23.00	665.28
P	STRUT,FR SUSP	X NM			1.00	452.00	23.00	348.04
M	GEAR & LINK ASSY,STEERING	BT			1.00	1444.00	23.00	1111.88

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ANDREW YAP MING HWEE Reg No/Reg Date SMW2051P / 09/11/202 Date In/Mileage / 0 Chassis No MMB5TA13AMH000618 Engine No 3A92UJP3584 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/12/2020/ 12:34		442 / Cocolu	61000

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M END ASSY, TIE ROD / 07	1.00	52.00	23.00	40.04

Estimate

Steve (LKK)
21/12/20, 3:39pmOO- NM AuL
EXCROSS - ?
15 d/s
P/P
My Belgy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by
Date:

7% GST on	18871.61	18,871.61
		1321.01
Total Payable		20,192.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.