

CYCLE & CARRIAGE
 Reg No : 199405410K

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08235/CHEW CHIN SENG Reg No/Reg Date SKD622D / 23/01/201 Date In/Mileage / 27761 Chassis No KNAF3416MK5027328 Engine No G4FGJH716014 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/12/2020/ 12:07	QUD	247 / DonBong	26096			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800 1600.00
RENEW ACCIDENT DAMAGED PARTS ON RH FRONT DOOR, RH MIRROR					400x1			
RH REAR DOOR, REPAIR RH REAR FENDER								120.00
E PNT88000								120.00
TRANSFER RH FRONT DOOR GLASS, DOOR TRIM, MECHANISM								
AND OTHERS ATTACHMENT TO NEW DOOR PANEL								
E PNT88000								120.00
TRANSFER RH REAR DOOR GLASS, DOOR TRIM, MECHANISM								
AND OTHERS ATTACHMENT TO NEW DOOR PANEL								
E PNT98000								2880.00
PAINT WORK SPRAY RH MIRROR, RH FRONT DOOR, RH REAR DOOR,					480 X 4 (CR5 color)			1920
RH REAR FENDER, RH SIDE SILL AND AFFECTED PORTION								
(CLEAR COAT)								80 120.00
M SUNDRY								30.00
APPLY BODY SEALANT								
A 54900099								80.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								120.00
PERFORM RUST PREVENTION								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP								400.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
SUPPLY RH REAR SPORT RIM								
M SUNDRY								50.00
LABOUR TO RENEW RH REAR SPORT RIM INCLUDING BALANCING								
M SUNDRY								
SUNDRIES								
M PANEL ASSY-FRONT DOOR, RH					1.00	1277.00	20.00	1021.60
M MOULDING ASSY-FRT DR FRAME, RH					1.00	37.00	20.00	29.60
M W/STRIP ASSY-FR DR BELT O/S RH					1.00	64.00	20.00	51.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08235/CHEW CHIN SENG Reg No/Reg Date SKD622D / 23/01/201 Date In/Mileage / 27761 Chassis No KNAF3416MK5027328 Engine No G4FGJH716014 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/12/2020/ 12:07	QUD	247 / DonBong	26096			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M GLASS ASSY-FRONT DOOR, RH					1.00	207.00	20.00	165.60
M PANEL ASSY-FRONT DR MODULE, LH					1.00	241.00	20.00	192.80
M MOTOR ASSY-FRONT POWER WDW, RH					1.00	362.00	20.00	289.60
M BLACK TAPE-FR DR, RR, RH					1.00	13.00	20.00	10.40
M BLACK TAPE-FR DR, RH					1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FRAME RR OTR,					1.00	8.00	20.00	6.40
M PANEL ASSY-REAR DOOR, RH					1.00	1377.00	20.00	1101.60
M W/STRIP ASSY-RR DR BELT O/S RH					1.00	60.00	20.00	48.00
M MOULDING ASSY-RR DR FRAME, RH					1.00	44.00	20.00	35.20
M FILM-ANTI CHIPPY RH					1.00	27.00	20.00	21.60
M MIRROR ASSY-OUTSIDE RR VIEW, RH					1.00	559.00	20.00	447.20

Estimate

SURVEYOR NAME: Steve CLKK)
SURVEYOR SIGNATURE: DO-NH Ant
DATE: Excess - ?
REMARKS: P/P
By Bel SPY
5 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

7% GST on	Nett	9,101.20
	9101.20	637.08
	Total Payable	9,738.28

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.