



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Dufu Industries Services Pte. L Reg No/Reg Date SLA3918K / 29/02/201 Date In/Mileage / 62280 Chassis No KNAGU411MG5034644 Engine No G4NDFH092301 Make/Model KIA/OPTIMA 2.0 A 707 Colour/Trim ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/12/2020/ 12:54	BLE	261 / Edwin Caina	26097			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHR DOOR REPAIR LHR FENDER 1/2					600			1600.00
E PNT98000 RESPRAY LHR DOOR & LHR FENDER								700.00
E PNT88000 REMOVE & REFIT LHR DOOR COMPONENT								120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								40 80.00
M SUNDRY Sundries								20 30.00
M HANDLE ASSY-DOOR OUTSIDE, LH					1.00	55.00	20.00	44.00
M PAD-DOOR OUTSIDE HANDLE, LH					1.00	3.00	20.00	2.40
M COVER-FR DR O/S HDL LH					1.00	25.00	20.00	20.00
M PAD-DOOR O/S HANDLE REAR, LH					1.00	3.00	20.00	2.40
M PANEL ASSY-REAR DOOR, LH					1.00	1307.00	20.00	1045.60
M MOULDING ASSY-RR DR FRAME, LH					1.00	132.00	20.00	105.60
M GARNISH ASSY-RR DR FR FRAME, LH					1.00	104.00	20.00	83.20
M GARNISH ASSY-RR DR RR FRAME, LH					1.00	126.00	20.00	100.80
M MOULDING-RR DR OPNG W/STRIP MT					1.00	22.00	20.00	17.60
M W/STRIP ASSY-RR DR BELT O/S LH					1.00	78.00	20.00	62.40

Estimate

SURVEYOR NAME: Steve CLKK

21/12/20, 4:00pm

SURVEYOR SIGNATURE: OD-Nat AL

EXCPT-7

DATE:

4181.60

SURVEYOR NAME : Steve CLKK
SURVEYOR SIGNATURE : OD - Not AL
DATE : 21/12/20, 4:30pm
EXCISE - ?

4181.60

Confirm & accepted by
LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
Authorized signatory and company stamp

PIP
By BCL Syg
4 dys

Nett 4,164.00
7% GST on 4164.00 291.48
Total Payable 4,455.48

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.