



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 21/12/20
LKK - STEVE

VEHICLE NO : SLA3918K

MODEL : KIA/OPTIMA 2.0 A

WIP : 26097

Material	:	\$	<u>1,421.60</u>
Labour	:	\$	<u>1,630.00</u>
Sub-Total	:	\$	<u>3,051.60</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>2,451.60</u>
GST 7%	:	\$	<u>171.61</u>
Grand Total	:	\$	<u>2,623.21</u>
Finalise By/Date : <u>Larry on 29/01/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 3 days (1 wk end +)
P.H

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 22/12/2020	<table> <tr> <td>Cust No/Name</td><td>/Dufu Industries Services Pte. L</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLA3918K / 29/02/2016</td></tr> <tr> <td>Date In/Mileage</td><td>22/12/2020/ 62280</td></tr> <tr> <td>Chassis/Package</td><td>KNAGU411MG5034644</td></tr> <tr> <td>Engine No</td><td>G4NDFH092301</td></tr> <tr> <td>Make/Model</td><td>KIA/OPTIMA 2.0 A 707</td></tr> <tr> <td>Colour/Trim</td><td>ABP / WK</td></tr> </table>	Cust No/Name	/Dufu Industries Services Pte. L	Reg No/Reg Date	SLA3918K / 29/02/2016	Date In/Mileage	22/12/2020/ 62280	Chassis/Package	KNAGU411MG5034644	Engine No	G4NDFH092301	Make/Model	KIA/OPTIMA 2.0 A 707	Colour/Trim	ABP / WK
Cust No/Name	/Dufu Industries Services Pte. L														
Reg No/Reg Date	SLA3918K / 29/02/2016														
Date In/Mileage	22/12/2020/ 62280														
Chassis/Package	KNAGU411MG5034644														
Engine No	G4NDFH092301														
Make/Model	KIA/OPTIMA 2.0 A 707														
Colour/Trim	ABP / WK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	29/01/2021/ 16:14	BLE	884 / Lauro Songcuan	26097

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LH REAR DOOR, REPAIR LH REAR FENDER				600.00 ✓
E PNT98000 SPRAY PAINT LH REAR DOOR & LH REAR FENDER				700.00 ✓
E PNT88000 REMOVE & REFIT LH REAR DOOR COMPONENTS				120.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00 ✓
USING HI-SCAN PRO TEST				
Ac SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X EXC EXCESS				-600.00
X HANDLE ASSY-DOOR OUTSIDE, LH ✓	1.00	55.00	20.00	44.00 ✓
X COVER-FR DR O/S HDL LH ✓	1.00	25.00	20.00	20.00 ✓
X PAD-DOOR O/S HANDLE REAR, LH ✓	1.00	3.00	20.00	2.40 ✓
X PANEL ASSY-REAR DOOR, LH ✓	1.00	1307.00	20.00	1045.60 ✓
X MOULDING ASSY-RR DR FRAME, LH ✓	1.00	132.00	20.00	105.60 ✓
X GARNISH ASSY-RR DR FR FRAME, LH ✓	1.00	104.00	20.00	83.20 ✓
X GARNISH ASSY-RR DR RR FRAME, LH ✓	1.00	126.00	20.00	100.80 ✓
X FILM-RR DR ANTI CHIPPING, LH ✓	1.00	14.00	20.00	11.20 X
X FILM-ANTI CHIPP LG LH ✓ <i>supp.</i>	1.00	8.00	20.00	6.40 X
X PAD-DOOR OUTSIDE HANDLE, LH ✓	1.00	3.00	20.00	2.40 ✓
Z TEXT OD CLAIM - AIG SURVEY: STEVE 21.12.2020 DOA: 20.12.2020 04 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	1,421.60			
Labour	1,570.00			
Standard Menu	0.00	7% GST on	2451.60	171.61
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	-540.00			
Total(w/o GST)	2,451.60		Total Payable	2,623.21

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SLA 3918 K

<u>Materials</u>		<u>Cost \$</u>	
1	Film- RR DR Anti Chipping, LH	14.00	✓ nec
	Film- Anti Chippg LH	8.00	✓ nec
		22.00	
20% Discount		4.40	
		17.60	
7% GST		1.23	
Total		18.83	

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SLA3918K

WIP: 26097 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	WATER PUMP	? / SUPP			
2	WATER PUMP	? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	24/12/10	Steve
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OPTIMA

SURVEYOR: STEVE

HOME
 Online
OPTIMA(JF)/2016/G 2.0 CVV..
VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

EPS
 AIRCON
 AIRBAG

7/7

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
EPB	No Current DTC	Good
ESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0235	VCI Ver.	02.48
ECU Ver.	M-E-K-01-00-0176	OS Ver.	Android 9

HOME
 Online
OPTIMA(JF)/2016/G 2.0 CVV..
VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

EPS
 AIRCON
 AIRBAG

7/7

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
EPB	No Current DTC	Good
ESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0235	VCI Ver.	02.48
ECU Ver.	M-E-K-01-00-0176	OS Ver.	Android 9