LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Tan Kah Leong Date: 12 Jan 2021

Preliminary Advice

Insured Vehicle No : GBF1236A

TP Vehicle No : SMM3602X Accident Date : 18/12/2020 Make : LEXUS RX Assignment Date : 12/01/2021

Date of Inspection : 06/01/2021 Est. Duration of Repair : 4

Inspection At : EURO SUCCESS SERVICES PTE LTD (HQ)

1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY

SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

(x) Other comments: Survey on wp

Repairer's Estimate (Gross)	:S\$	25,244.00
Revised Amount	:S\$	4,000.33
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,000.33
Lump Sum Repair	:S\$	3,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.