

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SMM3602X

Model: LEXUS RX450H

not Authorized
date
2/3 3200/4d
6/1/21
wh phb After rep.

QTY	List Items	Price \$
1	REAR TAILGATE 11	3750.00 X
1	REAR TAILGATE GLASS MOULDING 11	345.00 X
1	REAR TAILGATE INNER LOCK 11	740.00 X
1	REAR TAILGATE STRIKER LOCK 11	250.60 X
1	REAR TAILGATE OUTER HANDLE 11	250.30 X
1	REAR TAILGATE EMBLEM 11	78.80 X
1	REAR TAILGATE HARRIER EMBLEM 11	68.80 X
1	REAR TAILGATE RX450H EMBLEM 11	68.90 X
2	REAR L-R TAILGATE LAMP @1750 11	3500.00 X
2	REAR L-R TAILLAMP @1650 11	3300.00 X
1	REAR TAILGATE INNER BOARD 11	1850.00 X
1	REAR TAILGATE RUBBER 11	250.00 X
1	REAR END PANEL 11 688.10	1150.00 ✓
1	REAR END PANEL INNER BOARD 11	927.60 X
1	REAR END PANEL SENSOR SWITCH	268.00 X
1	REAR BUMPER 11 955.10	2300.00 ✓
1	REAR BUMPER SPONGE 11 188.20	375.00 ✓
1	REAR BUMPER reinforcement 11 752.30	900.00 ✓
1	REAR BUMPER LOWER PAD KIT 11	980.00 X
2	REAR L-R BUMPER RETAINER @89.6 11	179.20 X
TOTAL		\$21,532.20
LESS 10%		\$2,153.22
TOTAL		\$19,379.00

Sepcial Nett Items		
1 SET	REAR BUMPER SENSOR 11 800.00 200	
1 SET	REAR BUMPER CLIP 11 45.00 ✓	
1 SET	REAR TAILGATE INNER BOARD CLIP 11 45.00 X	
1 SET	REAR END PANEL INNER BOARD CLIP 11 45.00 X	
1	REAR TAILGATE GLASS SEALANT 11 80.00 X	
1	REAR NUMBER PLATE WITH BOX 11 50.00 X	
		\$1,065.00

Labour Charges

TO REMOVE & REFIX REAR WINDSCREEN GLASS	11 200.00 X
TO APPLY UNDERCOATING ON ACCIDENT AFFECTED PARTS	350.00 30
TO TRANSFER REAR TAILGATE MECHANISM TO FACILIATE REPAIR	11 150.00 X
TO DISMENTLE & REPLACING REVERSE SENSOR	100.00 50
TO PROVIDE LABOUR, WORKMANSHIP TO DISMENTLE THE ABOVE MENTIONED PARTS INCLUDE OF CUT, WELD AND RE ALIGN BODY	2000.00 700

STRUCTURE AND DAMAGE PARTS CAUSED BY THE ACCIDENT
TO RESPRAY PAINT ON ACCIDENT AFFECTED PARTS

2000.00 650

\$4,800.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$25,244.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25837
102
P- 2325.33
S.N. 245
L- 1430
4020.33
202
3200