

ASS. REC. BY:

REF:

FCL

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Optimp

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8118k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 18 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Snp 9017E Yr Regn: 10, 19.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Toy Noah c.c. 1797Colour: Mr P. White A/C: Insured / Std / NI / NASp. Reading: 87.492 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR80 0390537Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Blm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pennwide

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 17/12/20 D.O.I. 21/12/2020Survey held at ✓Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or8/101

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/12 Review Video, wksp said no video footage

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Fees:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Date: 18.12.2020
 Vehicle No: SMP9017E
 Model: TOYOTA NOAH HYBRID 1.8X CVT
 Chassis: ZWR800390537-2019
 Reg.Year: 2019

Third Party Insurer: FIRST CAP
 Third Party Veh No: SHC2759X
 Date of Accident: 17.12.2020

Not Authorized
18 days
21 days
Running After Pain

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1	R	\$1,988.80
2	REAR TAILGATE "HYBRID" EMBLEM	1	R	\$85.80
3	REAR TAILGATE INNER TRIM	1	Bu	\$570.00
4	REAR TAILGATE INNER LOCK	1	De	\$495.20
5	REAR TAILGATE RUBBER	1	Di/De	\$380.70
6	REAR WINDSCREEN MOULDING	1	Ru	\$116.00
7	REAR BUMPER	1	R	\$823.00
8	REAR BUMPER SIDE BRACKET LH	1	Ru	\$156.70
9	REAR BUMPER SIDE BRACKET RH	1	Di	\$156.70
10	REAR BUMPER FIXING COVER RH	1	CM	\$38.40
11	REAR BUMPER REFLECTOR COVER RH	1	CM	\$124.80
12	REAR TAIL LAMP LOWER GARNISH COVER LH	1	Ru	\$197.80
13	REAR TAIL LAMP LOWER GARNISH COVER RH	1	Bu	\$197.80
14	REAR TAIL LAMP LOWER GARNISH COVER BRACKET LH	1	Ru	\$115.20
15	REAR TAIL LAMP LOWER GARNISH COVER BRACKET RH	1		\$115.20
16	REAR END PANEL	1	R	\$914.60
17	REAR END PANEL UPPER COVERING	1	Mg Di	\$207.30
18	REAR SPARE TYRE PANEL	1		\$698.00
19	REAR SPARE TYRE PANEL UPPER BOARD	1	CM	\$830.00
20	REAR SPARE TYRE INNER TRIM	1	Deform	\$730.00
21	REAR QUARTER PANEL INNER TRIM LH	1	Bu	\$582.00
22	REAR QUARTER PANEL INNER TRIM RH	1	Bu	\$582.00
23	REAR AXLE BEAM	1	Ru	\$3,280.00
24	REAR ABSORBER LH	1	Ru	\$235.00
25	REAR ABSORBER RH	1	Ru	\$235.00
26	FRONT BONNET	1	Bu	\$857.00
27	FRONT BONNET INSULATOR	1	Ru	\$280.00
28	FRONT BONNET HINGE LH	1	Di	\$59.00
29	FRONT BONNET HINGE RH	1	Di	\$59.00
30	FRONT BONNET GARNISH MOULDING	1	De	\$491.00
31	FRONT HEADLAMP LH	1	Mg CM	\$2,640.50
32	FRONT HEADLAMP RH	1		\$2,640.50
33	FRONT HEADLAMP UPPER PANEL LH	1	Bu	\$250.80
34	FRONT HEADLAMP UPPER PANEL RH	1	Bu	\$250.80
35	FRONT HEADLAMP GARNISH COVER LH	1		\$122.00
36	FRONT HEADLAMP GARNISH COVER RH	1		\$122.00

Head office

6 Kung Chong Road Singapore 150143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

37	FRONT BUMPER	1	Ben	\$920.00	✓
38	FRONT BUMPER SIDE BRACKET LH	1		\$97.40	?
39	FRONT BUMPER SIDE BRACKET RH	1		\$97.40	?
40	FRONT BUMPER LOWER GRILLE	1		\$372.80	?
41	FRONT BUMPER REINFORCEMENT	1		\$310.00	?
42	FRONT BUMPER ABSORBER FOAM	1		\$78.00	?
43	FRONT WIPER AIR GRILLE GARNISH COVER LH	1		\$69.00	?
44	FRONT WIPER AIR GRILLE GARNISH COVER RH	1		\$69.00	?
45	FRONT GRILLE BASE	1	cm	\$1,030.00	✓
46	FRONT GRILLE GARNISH MOULDING ASSEMBLY	1	cm	\$1,351.00	✓
47	FRONT FENDER LH	1	h	\$780.00	x
48	FRONT FENDER RH	1	h	\$780.00	x
49	FRONT FENDER "HYBRID" EMBLEM LH	1	h	\$79.00	✓
50	FRONT FENDER "HYBRID" EMBLEM RH	1	h	\$79.00	✓
51	FRONT SUPPORT PANEL	1	h	\$1,734.00	✓
52	FRONT AIR CLEANER BOX	1		\$1,586.00	?
53	FRONT AIR RESONATOR	1		\$241.00	?
54	FRONT AIRCON CONDENSER	1		\$1,351.00	?
55	FRONT AIRCON CONDENSER PRESSURE PIPE	1	h	\$533.00	x
56	FRONT AIRCON CONDENSER LIQUID TUBE	1	h	\$794.00	x
57	FRONT RADIATOR	1		\$1,987.00	?
58	FRONT RADIATOR TOP HOSE	1	h	\$67.00	x
59	FRONT RADIATOR BOTTOM HOSE	1	h	\$51.00	x
60	FRONT RADIATOR FAN SHROULD	1	h	\$253.00	x
61	FRONT RADIATOR FAN BLADE	1	h	\$242.00	x
62	FRONT RADIATOR FAN MOTOR	1	h	\$562.00	x
63	FRONT DOOR LH	1		REPAIR	
64	FRONT DOOR RH	1		REPAIR	
SUB TOTAL				\$37,142.20	
LESS 25%				-\$9,285.55	
PARTS TOTAL				\$27,856.65	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

5A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.12.2020
 Vehicle No: SMP9017E
 Model: TOYOTA NOAH HYBRID 1.8X CVT
 Chassis: ZWR800390537-2019
 Reg.Year: 2019

Third Party Insurer: FIRST CAP
 Third Party Veh No: SHC2759X
 Date of Accident: 17.12.2020

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM CLIPS	1		<i>na</i> \$50.00 ✓
2	REAR WINDSCREEN SEALANT	1	<i>na</i>	<i>401n</i> \$80.00
3	REAR END PANEL JOINT SEALANT	1		<i>na</i> \$60.00 <i>301n</i>
4	REAR BUMPER REVERSE SENSOR	1		<i>na</i> \$300.00 <i>201n</i>
5	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
6	REAR END PANEL UPPER COVERING CLIPS	1		<i>na</i> \$35.00 ✓
7	FRONT BONNET INSULATOR CLIPS	1		<i>na</i> \$40.00 ✓
8	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
9	FRONT RADIATOR COOLANT	1		<i>na</i> \$60.00 <i>301n</i>
			S/N TOTAL	\$725.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT & REAR ACCIDENT AREAS & ETC.

1800
\$2,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL, REAR TAIL LAMP GARNISH COVER LH, REAR TAIL LAMP LOWER GARNISH COVER RH, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

2000
\$2,600.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

120
\$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60
\$120.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

50
\$100.00

LABOUR CHARGES TO REMOVE & REPLACE REAR AXLE BEAM, REAR ABSORBER LH & ETC.

na \$300.00 X

TO WHEEL ALIGNMENT & BALANCING.

na \$80.00 X

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

TO TUFF KOTE & UNDERSEAL MATERIALS	\$200.00	1201
TO REFILL AIRCON GAS.	\$80.00	✓
TO DIAGNOSIS FAULTY CODE & RESET MEMORY.	\$150.00	?
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$120.00	401

LABOUR TOTAL	\$5,900.00
--------------	------------

TingAn

TOTAL	\$34,481.65
-------	-------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/12/2020 09:38 (SGT)
Date of Accident 17/12/2020 13:09 (SGT)
Exact Location of Accident AYE, Singapore
Additional Location Information Towards Town
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMP9017E

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner MS CARZ LEASING PTE LTD
Company Reg No 2XXXXX066R
Email Address kelly.yap@msgroup.com.sg
Mobile Phone No (Phone) +65-93854718
Alternative Phone No +65-97666288

VEHICLE PARTICULARS

Manufacturer Toyota
Model Noah
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance
Type of Coverage Comprehensive
Fleet Policy No
Policy Number SD20V10948/VPZ/R00
Cover Note Number -

DRIVER

Name of Driver Charlie Yuan Yi Kui
NRIC No SXXXX975H
Date Of Birth 09/01/1982
Occupation Outdoor

Date Of Driving Pass 29/01/2008
 Driving experience 12 YEARS AND 11 MONTHS
 Gender Male
 Mobile Number (Phone) +65-90918423
 Alt. Phone Number -
 Email Address charlie.yuan.09@gmail.com
 Address Blk 802C Keat Hong Close #05-63
 Address complement -
 Postcode 683802
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 4
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? No
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 5
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Yes

PASSENGER 1

Name Khoo Mei Shan
 Gender Female

PASSENGER 2

Name Chloe Yuan Xin Hui
 Gender Female

PASSENGER 3

Name Candy Cheong Zhi Min
 Gender Female

PASSENGER 4

Name Mandy Cheong Zhi Ling
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Rochor Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18002949999
 Alt. Police Station Phone No (Fax) +65-63918583
 Police Station Address 11 Kampong Kapor Road Singapore 208678
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

Refer to Police Report: T/20201217/2140.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC2759X
 Vehicle Manufacturer Hyundai
 Vehicle Model I30
 Vehicle Variant -
 Vehicle Colour Blue
 Vehicle Category Taxi
 Name of Driver Mohd Sinari Bin Abdul Rahman
 NRIC No SXXXX419J
 Contact Number (Phone) +65-90619593
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMV2050Y
 Vehicle Manufacturer Peugeot
 Vehicle Model 3008
 Vehicle Variant -
 Vehicle Colour Black
 Vehicle Category Private car
 Name of Driver LIM KIM SAN
 NRIC No SXXXX312D
 Contact Number (Phone) +65-96610770
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLP4231Y
 Vehicle Manufacturer Toyota
 Vehicle Model Vios
 Vehicle Variant -
 Vehicle Colour Gray
 Vehicle Category Private car
 Name of Driver NG NAM SENG
 NRIC No SXXXX476F
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT: 7/20201217/2140.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: ATTUYN
NRIC/FIN No.:

GIARMC SketchPlanForm_V3



SINGAPORE POLICE FORCE



T/20201217/2140

1 of 5

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

Report No. T/20201217/2140

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/12/2020 22:54	Vide Report No.:	Station Diary No.: 101
--	------------------	---------------------------

Informant's Particulars

Name of Informant: CHARLIE YUAN YI KUI			Address: APT BLK 802C KEAT HONG CLOSE #05-63 SINGAPORE 683802	
ID Type / ID No.: NRIC NO / S8201975H			Contact No.: Home/Office:	Mobile: 90918423
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 38	Date of Birth: 09/01/1982	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 17/12/2020 13:10	Type of Location: EXPRESS WAY
Location: AYER RAJAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC2759X		HYUNDAI	AE IONIQ HEV FL 1.6 DCT	Blue	Slightly Damaged	0
SLP4231Y	Car	TOYOTA	VIOS 1.5E CVT	Grey	Slightly Damaged	0
SMP9017E	Car	TOYOTA	NOAH HYBRID 1.8X CVT	White	Slightly Damaged	4



Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

CONTINUATION OF REPORT

Driver			
Name	LIM KIM SAN	ID No.	S7144312D
Related Vehicle	SMV2050Y (Car)	Contact No.	96610770
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/12/2020 around 1310hrs, I was travelling on the AYE towards the city direction. I was travelling on the second lane from the right when suddenly the car in front of me jam break. I also jam break and immediately came to a stop. Not long after, I felt a large impact coming from behind. My wife who was seating behind with my three kids fell from her seat due to the impact however my 3 kids were held in place by the seatbelt. I came down from my vehicle to find out what had happen. I discovered that my vehicle was involve in a chain collision.

My car SMP9017E was sandwiched in between SHC2759X who had collided on the rear of my vehicle and SMV2050Y which my vehicle front had collided into. The car SMV2050Y front has also collided onto the rear of vehicle SLP4231Y. After checking that all parties are alright and damages to all vehicles are light. We exchange particulars among all the drivers after which we all drive off.

Damages to my car was that my front bonnet was dented in and rear bumper was also dented in. Scratches and paint chips is around the impact area.. I am lodging this report for insurance claim purposes.