

Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

Not Authorized
18 days
21 Sep 87
Recovery After Pain

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR TAILGATE	1	Ry	\$1,988.80	✓
2	REAR TAILGATE "HYBRID" EMBLEM	1	nu	\$85.80	✓
3	REAR TAILGATE INNER TRIM	1	Bu	\$570.00	✓
4	REAR TAILGATE INNER LOCK	1	nu	\$495.20	✓
5	REAR TAILGATE RUBBER	1	Dir/nu	\$380.70	✓
6	REAR WINDSCREEN MOULDING	1	nu	\$116.00	✓
7	REAR BUMPER	1	Ry	\$823.00	✓
8	REAR BUMPER SIDE BRACKET LH	1	nu	\$156.70	X
9	REAR BUMPER SIDE BRACKET RH	1	Dir	\$156.70	✓
10	REAR BUMPER FIXING COVER RH	1	CM	\$38.40	✓
11	REAR BUMPER REFLECTOR COVER RH	1	CM	\$124.80	✓
12	REAR TAIL LAMP LOWER GARNISH COVER LH	1	nu	\$197.80	X
13	REAR TAIL LAMP LOWER GARNISH COVER RH	1	Bu	\$197.80	✓
14	REAR TAIL LAMP LOWER GARNISH COVER BRACKET LH	1	nu	\$115.20	X
15	REAR TAIL LAMP LOWER GARNISH COVER BRACKET RH	1		\$115.20	?
16	REAR END PANEL	1	Ry	\$914.60	✓
17	REAR END PANEL UPPER COVERING	1	nu Dir	\$207.30	✓
18	REAR SPARE TYRE PANEL	1		\$698.00	?
19	REAR SPARE TYRE PANEL UPPER BOARD	1	CM	\$830.00	✓
20	REAR SPARE TYRE INNER TRIM	1	Reform	\$730.00	✓
21	REAR QUARTER PANEL INNER TRIM LH	1	Bu	\$582.00	✓
22	REAR QUARTER PANEL INNER TRIM RH	1	Bu	\$582.00	✓
23	REAR AXLE BEAM	1	nu	\$3,280.00	X
24	REAR ABSORBER LH	1	nu	\$235.00	X
25	REAR ABSORBER RH	1	nu	\$235.00	X
26	FRONT BONNET	1	Bu	\$857.00	✓
27	FRONT BONNET INSULATOR	1	nu	\$280.00	X
28	FRONT BONNET HINGE LH	1	Dir	\$59.00	✓
29	FRONT BONNET HINGE RH	1	Dir	\$59.00	✓
30	FRONT BONNET GARNISH MOULDING	1	nu	\$491.00	✓
31	FRONT HEADLAMP LH	1	nu CM	\$2,640.50	✓
32	FRONT HEADLAMP RH	1		\$2,640.50	✓
33	FRONT HEADLAMP UPPER PANEL LH	1	Bu	\$250.80	✓
34	FRONT HEADLAMP UPPER PANEL RH	1	Bu	\$250.80	✓
35	FRONT HEADLAMP GARNISH COVER LH	1		\$122.00	?
36	FRONT HEADLAMP GARNISH COVER RH	1		\$122.00	?

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.12.2020
 Vehicle No: SMP9017E
 Model: TOYOTA NOAH HYBRID 1.8X CVT
 Chassis: ZWR800390537-2019
 Reg.Year: 2019

Third Party Insurer: FIRST CAP
 Third Party Veh No: SHC2759X
 Date of Accident: 17.12.2020

37	FRONT BUMPER	1	Br	\$920.00	✓
38	FRONT BUMPER SIDE BRACKET LH	1		\$97.40	?
39	FRONT BUMPER SIDE BRACKET RH	1		\$97.40	?
40	FRONT BUMPER LOWER GRILLE	1		\$372.80	?
41	FRONT BUMPER REINFORCEMENT	1		\$310.00	?
42	FRONT BUMPER ABSORBER FOAM	1		\$78.00	?
43	FRONT WIPER AIR GRILLE GARNISH COVER LH	1		\$69.00	?
44	FRONT WIPER AIR GRILLE GARNISH COVER RH	1		\$69.00	?
45	FRONT GRILLE BASE	1	CM	\$1,030.00	✓
46	FRONT GRILLE GARNISH MOULDING ASSEMBLY	1	CM	\$1,351.00	✓
47	FRONT FENDER LH	1	R	\$780.00	X
48	FRONT FENDER RH	1	R	\$780.00	X
49	FRONT FENDER "HYBRID" EMBLEM LH	1	Rec	\$79.00	✓
50	FRONT FENDER "HYBIRD" EMBLEM RH	1	Rec	\$79.00	✓
51	FRONT SUPPORT PANEL	1	Br	\$1,734.00	✓
52	FRONT AIR CLEANER BOX	1		\$1,586.00	?
53	FRONT AIR RESONATOR	1		\$241.00	?
54	FRONT AIRCON CONDENSER	1		\$1,351.00	?
55	FRONT AIRCON CONDENSER PRESSURE PIPE	1	P _h	\$533.00	X
56	FRONT AIRCON CONDENSER LIQUID TUBE	1	S _h	\$794.00	X
57	FRONT RADIATOR	1		\$1,987.00	?
58	FRONT RADIATOR TOP HOSE	1	P _h	\$67.00	X
59	FRONT RADIATOR BOTTOM HOSE	1	S _h	\$51.00	X
60	FRONT RADIATOR FAN SHROULD	1	P _h	\$253.00	X
61	FRONT RADIATOR FAN BLADE	1	S _h	\$242.00	X
62	FRONT RADIATOR FAN MOTOR	1	S _h	\$562.00	X
63	FRONT DOOR LH	1		REPAIR	
64	FRONT DOOR RH	1		REPAIR	
				SUB TOTAL	\$37,142.20
				LESS 25%	-\$9,285.55
				PARTS TOTAL	\$27,856.65

Date: 18.12.2020
 Vehicle No: SMP9017E
 Model: TOYOTA NOAH HYBRID 1.8X CVT
 Chassis: ZWR800390537-2019
 Reg.Year: 2019

Third Party Insurer: FIRST CAP
 Third Party Veh No: SHC2759X
 Date of Accident: 17.12.2020

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM CLIPS	1		<i>na</i> \$50.00 ✓
2	REAR WINDSCREEN SEALANT	1	<i>na</i>	<i>401n</i> \$80.00
3	REAR END PANEL JOINT SEALANT	1		<i>na</i> \$60.00 <i>301n</i>
4	REAR BUMPER REVERSE SENSOR	1		<i>na</i> \$300.00 <i>201n</i>
5	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
6	REAR END PANEL UPPER COVERING CLIPS	1		<i>na</i> \$35.00 ✓
7	FRONT BONNET INSULATOR CLIPS	1		<i>na</i> \$40.00 ✓
8	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
9	FRONT RADIATOR COOLANT	1		<i>na</i> \$60.00 <i>301n</i>
			S/N TOTAL	\$725.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT & REAR ACCIDENT AREAS & ETC.

1800
\$2,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL, REAR TAIL LAMP GARNISH COVER LH, REAR TAIL LAMP LOWER GARNISH COVER RH, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

2000
\$2,600.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

120
\$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60
\$120.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

50
\$100.00

LABOUR CHARGES TO REMOVE & REPLACE REAR AXLE BEAM, REAR ABSORBER LH & ETC.

na \$300.00 X

TO WHEEL ALIGNMENT & BALANCING.

na \$80.00 X

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

TO TUFF KOTE & UNDERSEAL MATERIALS	\$200.00	1201
TO REFILL AIRCON GAS.	\$80.00	✓
TO DIAGNOSIS FAULTY CODE & RESET MEMORY.	\$150.00	?
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$120.00	401

LABOUR TOTAL	\$5,900.00
--------------	------------

TingAn	TOTAL	\$34,481.65
--------	-------	-------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1903

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

