

Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

*Not Notified
11 days 820,200
18 days After Kain*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT	AMOUNT S\$	
1	REAR TAILGATE	1	Ry	\$1,988.80	✓
2	REAR TAILGATE "HYBRID" EMBLEM	1	Ry	\$85.80	✓
3	REAR TAILGATE INNER TRIM	1	Bu	\$570.00	✓
4	REAR TAILGATE INNER LOCK <i>467.60</i>	1	Del	\$495.20	✓
5	REAR TAILGATE RUBBER	1	Di/1 Del	\$380.70	✓
6	REAR WINDSCREEN MOULDING	1	Ry	\$116.00	✓
7	REAR BUMPER	1	Ry	\$823.00	✓
8	REAR BUMPER SIDE BRACKET LH	1	Ry	\$156.70	X
9	REAR BUMPER SIDE BRACKET RH	1	Di/1	\$156.70	✓
10	REAR BUMPER FIXING COVER RH	1	CM	\$38.40	✓
11	REAR BUMPER REFLECTOR COVER RH	1	CM	\$124.80	✓
12	REAR TAIL LAMP LOWER GARNISH COVER LH	1	Sm	\$197.80	X
13	REAR TAIL LAMP LOWER GARNISH COVER RH	1	Bu	\$197.80	✓
14	REAR TAIL LAMP LOWER GARNISH COVER BRACKET LH	1	Sm	\$115.20	X
15	REAR TAIL LAMP LOWER GARNISH COVER BRACKET RH	1	R	\$115.20	X
16	REAR END PANEL <i>795.90</i>	1	Ry	\$914.60	✓
17	REAR END PANEL UPPER COVERING	1	My Di/1	\$207.30	✓
18	REAR SPARE TYRE PANEL	1	Ry	\$698.00	✓
19	REAR SPARE TYRE PANEL UPPER BOARD	1	CM	\$830.00	✓
20	REAR SPARE TYRE INNER TRIM	1	Deform	\$730.00	✓
21	REAR QUARTER PANEL INNER TRIM LH	1	Bu	\$582.00	✓
22	REAR QUARTER PANEL INNER TRIM RH	1	Bu	\$582.00	✓
23	REAR AXLE BEAM	1	Sm	\$3,280.00	X
24	REAR ABSORBER LH	1	Sm	\$235.00	X
25	REAR ABSORBER RH	1	Sm	\$235.00	X
26	FRONT BONNET	1	Bu	\$857.00	✓
27	FRONT BONNET INSULATOR	1	Ry	\$280.00	X
28	FRONT BONNET HINGE LH	1	Di/1	\$59.00	✓
29	FRONT BONNET HINGE RH	1	Di/1	\$59.00	✓
30	FRONT BONNET GARNISH MOULDING	1	De	\$491.00	✓
31	FRONT HEADLAMP LH	1	My CM	\$2,640.50	✓
32	FRONT HEADLAMP RH	1	"	\$2,640.50	✓
33	FRONT HEADLAMP UPPER PANEL LH	1	Bu	\$250.80	✓
34	FRONT HEADLAMP UPPER PANEL RH	1	Bu	\$250.80	✓
35	FRONT HEADLAMP GARNISH COVER LH	1	Sm	\$122.00	X
36	FRONT HEADLAMP GARNISH COVER RH	1	Sm	\$122.00	X

Head office

5 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 56047
Tel: (+65) 6461 1522 | Fax: (+65) 6461 1011



Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg. Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

37	FRONT BUMPER	835.90	1	Bu	\$920.00	✓
38	FRONT BUMPER SIDE BRACKET LH		1	R	\$97.40	X
39	FRONT BUMPER SIDE BRACKET RH		1	R	\$97.40	X
40	FRONT BUMPER LOWER GRILLE		1	Sn	\$372.80	X
41	FRONT BUMPER REINFORCEMENT		1	Bu	\$310.00	✓
42	FRONT BUMPER ABSORBER FOAM		1	Sn	\$78.00	X
43	FRONT WIPER AIR GRILLE GARNISH COVER LH		1	Sn	\$69.00	X
44	FRONT WIPER AIR GRILLE GARNISH COVER RH		1	Sn	\$69.00	X
45	FRONT GRILLE BASE	635.10	1	CM	\$1,030.00	✓
46	FRONT GRILLE GARNISH MOULDING ASSEMBLY	1036.20	1	CM	\$1,351.00	✓
47	FRONT FENDER LH		1	R	\$780.00	X
48	FRONT FENDER RH		1	R	\$780.00	X
49	FRONT FENDER "HYBRID" EMBLEM LH		1	Rex	\$79.00	✓
50	FRONT FENDER "HYBRID" EMBLEM RH		1	Rn	\$79.00	✓
51	FRONT SUPPORT PANEL	1211.10	1	Ry	\$1,734.00	✓
52	FRONT AIR CLEANER BOX	455.90	1	Rd	\$1,586.00	✓
53	FRONT AIR RESONATOR		1	Sn	\$241.00	X
54	FRONT AIRCON CONDENSER		1	Sn	\$1,351.00	X
55	FRONT AIRCON CONDENSER PRESSURE PIPE		1	Sn	\$533.00	X
56	FRONT AIRCON CONDENSER LIQUID TUBE		1	Sn	\$794.00	X
57	FRONT RADIATOR	1552.30	1	Pu	\$1,987.00	✓
58	FRONT RADIATOR TOP HOSE		1	Sn	\$67.00	X
59	FRONT RADIATOR BOTTOM HOSE		1	Sn	\$51.00	X
60	FRONT RADIATOR FAN SHROULD		1	Sn	\$253.00	X
61	FRONT RADIATOR FAN BLADE		1	Sn	\$242.00	X
62	FRONT RADIATOR FAN MOTOR		1	Sn	\$562.00	X
63	FRONT DOOR LH		1		REPAIR	
64	FRONT DOOR RH		1		REPAIR	

SUB TOTAL	\$37,142.20
LESS 25%	-\$9,285.55
PARTS TOTAL	\$27,856.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2152

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
8K 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2152

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
8K 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM CLIPS	1	nr	\$50.00
2	REAR WINDSCREEN SEALANT	1	nr	\$80.00
3	REAR END PANEL JOINT SEALANT	1	nr	\$60.00
4	REAR BUMPER REVERSE SENSOR	1	nr	\$300.00
5	REAR BUMPER CLIPS	1	nr	\$50.00
6	REAR END PANEL UPPER COVERING CLIPS	1	nr	\$35.00
7	FRONT BONNET INSULATOR CLIPS	1	nr	\$40.00
8	FRONT BUMPER CLIPS	1	nr	\$50.00
9	FRONT RADIATOR COOLANT	1	nr	\$60.00
			S/N TOTAL	\$725.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT & REAR ACCIDENT AREAS & ETC.

1800
\$2,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL, REAR TAIL LAMP GARNISH COVER LH, REAR TAIL LAMP LOWER GARNISH COVER RH, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

2000
\$2,600.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

120
\$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60
\$120.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

50
\$100.00

LABOUR CHARGES TO REMOVE & REPLACE REAR AXLE BEAM, REAR ABSORBER LH & ETC.

nr \$300.00 X

WHEEL ALIGNMENT & BALANCING.

nr \$80.00 X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1213 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

TO TUFF KOTE & UNDERSEAL MATERIALS

\$200.00 1201

TO REFILL AIRCON GAS.

\$80.00 ✓

TO DIAGNOSIS FAULTY CODE & RESET MEMORY.

na \$150.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 401

LABOUR TOTAL \$5,900.00

TingAn

TOTAL \$34,481.65

Head office

6 Yung Chung Road Singapore 150143
Tel: (+65) 6472 1913 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 0019 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 26.12.2020
Vehicle No: SMP9017E
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800390537-2019
Reg.Year: 2019

Third Party Insurer: FIRST CAP
Third Party Veh No: SHC2759X
Date of Accident: 17.12.2020

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR SPARE TYRE EXTENTION PANEL RH	1		<i>R</i> \$698.00
2	REAR AIRCON BLOWER ASSY	1	<i>hurt cm</i>	\$1,500.00
SUB TOTAL				\$2,198.00
LESS 25%				-\$549.50
PARTS TOTAL				\$1,648.50

SUPPLEMENTARY

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, READJUST REAR SPARE TYRE
EXTENTION PANEL RH, REAR AIRCON BLOWER ASSY & ETC.

100%
\$200.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
AT REAR SPARE TYRE EXTENTION PANEL RH & ETC.

NA \$200.00 *X*

LABOUR TOTAL \$400.00

TingAn TOTAL \$2,048.50

Finalise:

Parts: \$20705.63

Nett: \$525

Supp: \$1648.50

Labour: \$4670

Jump Sum: \$27549.13 less 20% — \$22039.30

↓

\$22000 *

Head office

5 Kung Chong Road Singapore 156143
Tel: (+65) 6472 1213 | Fax: (+65) 6472 2112

Branch

6A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9916 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

8K 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

