

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

21/12/2020 19:15

OWNER'S PARTICULARS

JOB-NO: 50113035

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHD8591S

TRANS: AUTO

CHASSIS: KMHLB41UMGU093794

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDEU461323

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	1,000.00	0.00	1,000.00		Y	<u>600</u>
2 SUNDRIES	1.00	50.00	0.00	50.00		Y	<u>20</u>
3 RUST PROOFING	1.00	80.00	0.00	80.00		Y	<u>40</u>
4 DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	180.00	0.00	180.00		Y	<u>60</u>
5 ADJUST HEADLAMP AIM	1.00	80.00	0.00	80.00		Y	<u>30</u>
6 R&R RADIATOR & CONDENSER & TURBO INTERCOOLER	1.00	180.00	0.00	180.00		Y	<u>80</u>
7 VACUUM & TOP UP AIR COND GAS R-134A	1.00	150.00	0.00	150.00		Y	<u>60</u>
8 R&R FRONT RIM & TYRE LH	1.00	120.00	0.00	120.00		Y	<u>X</u>
9 CONDUCT 4 WHEEL ALIGNMENT & BALANCING	1.00	150.00	0.00	150.00		Y	<u>X</u>
10 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	<u>200</u>
11 RESPRAY FRONT FENDER LH	1.00	250.00	0.00	250.00		Y	<u>200</u>
12 RESPRAY BONNET & BONNET HINGE LH	1.00	300.00	0.00	300.00		Y	<u>200</u>
13 RESPRAY SIDE SKIRT LH	1.00	250.00	0.00	250.00		Y	<u>X</u>
14 RESPRAY FRONT WHEELHOUSE PANEL LH	1.00	250.00	0.00	250.00		Y	<u>X</u>
TOTAL:		3,290.00	0.00	3,290.00			

MATERIALS

1 FRONT BUMPER <i>CR</i>	1.00	599.68	119.94	479.74	L	Y	
2 FRONT BUMPER TOP SEAL <i>new</i>	1.00	36.20	7.24	28.96	L	Y	
3 FRONT BUMPER LOWER LIP <i>old</i>	1.00	83.87	16.77	67.10	L	Y	
4 FRONT BUMPER AIR DUCT LH <i>X NN</i>	1.00	105.63	21.13	84.50	L	Y	
5 FRONT BUMPER RETAINER LH <i>CR</i>	1.00	48.32	9.66	38.66	L	Y	
6 FRONT BUMPER RETAINER RH <i>X NN</i>	1.00	48.32	9.66	38.66	L	Y	
7 FRONT BUMPER RADIATOR GRILLE <i>scr</i>	1.00	1,110.10	222.02	888.08	L	Y	
8 FRONT FENDER LH <i>st</i>	1.00	659.50	131.90	527.60	L	Y	
9 FRONT FENDER INNER SHIELD LH <i>X NN</i>	1.00	205.12	41.02	164.10	L	Y	
10 HEADLAMP LH <i>CR</i>	1.00	1,808.10	361.62	1,446.48	L	Y	
11 BONNET <i>repair</i>	1.00	1,812.68	362.54	1,450.14	L	Y	
12 BONNET HINGE LH <i>X NN</i>	1.00	61.85	12.37	49.48	L	Y	
13 FRONT WHEEL CAP LH <i>X NN</i>	1.00	265.50	53.10	212.40	L	Y	
14 FRONT SUPPORT PANEL <i>CR</i>	1.00	962.87	192.57	770.30	L	Y	
15 SIDE SKIRT LH <i>X NN</i>	1.00	695.88	139.18	556.70	L	Y	
16 FRONT BUMPER CLIP SET <i>new</i>	1.00	50.00	0.00	50.00 <u>30</u>	S	Y	
17 FRONT FENDER INNER SHIELD CLIP SET LH <i>X</i>	1.00	35.00	0.00	35.00	S	Y	

NN

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
18 REPAIR FRONT WHEEL HOUSE PANEL LH	1.00	0.00	0.00	0.00	S	Y	
19 FRONT TYRE LH NN NN	1.00	280.00	0.00	280.00	S	Y	
20 RADIATOR COOLANT ver	1.00	60.00	0.00	30 60.00 40	S	Y	
TOTAL:		8,928.62	1,700.72	7,227.90			

TOTAL PARTS & LABOUR : 12,218.62 1,700.72 10,517.90

EXCESS/LOADING: \$ 0.00

No. Of Day:

5 days

RE-SURVEY: BEFORE/ AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 22 / 12 / 2000 P1545

SURVEYED BY:

Ramon

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Lumpsum

Labour → \$1,490

S/N → \$70

Parts → \$4,246.92

L + S + P → \$5,806.92 - 20%

= \$4,645.54

Final Amt → \$4,645.54

L/S = \$4,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: