

ComfortDelGro Engineering

205 Braddell Road S(579701)

Type of Claim : \_\_\_\_TP

### **ACCIDENT REPAIR ESTIMATE**

Vehicle No.

SMM4972X

Our Ref:

		Make & Model : HYUNDAI AD AVANTE 1.6 G
		Year of Manufacture : 2019
		Chassis No. KMHD841CMKU91030
ins Company : INDIA VS	CHINA TAIPING	Engine No. G4FGKU146835
Excess	<del></del>	Policy No.
Date of Accident 10 08	.12.2020	Time of Accident : 07:20
Suggested Days of Repair		In-house Vehicle Assessor
Repair Estimate		Case Owner
		Signature :
Parts (a) Cost / List Price Items	<u> </u>	Contact No
Plus/Less 20%	\$ -	Spark Car Care Service Reception
		63837103 – Patrick Tia
Total of Cost / List	\$	PatrickTia@sparkcarcare.com
(b) Nett Price Items	s -	63837730 - Brenda Ng BrendaNg@sparkcarcare.com
(2) New Med Rems		63837466 – Rohani
Less		RohaniM@sparkcarcare.com
Total of Nett Item	3	Workshop Operation
(c) Special Nett Items	\$ -	63837656 - Ngo Toh Wee Ngotw@sparkcarcare.com
(c) Special Nett Items	Ψ -	63838115 - William Wang
Total Parts Cost (Appendix A)	\$ -	WilliamWangKS@sparkarcare.com
Labour (Annondiu D)	\$ 710.00	63837362 - Andrew Goh
Labour (Appendix B)	\$ 710.00	AndrewCorneliusGoh@sparkcarcare.com
Total Repair Cost	\$ 710.00	
The above total will be subjected t	% 7% G.S.T.	
Name of Surveyor		
Company	<u> </u>	
Survey conducted on		_atat
Remarks By Surveyor		
(a) The repair of this vehicle is	authorized / is not au	uthorized until further notice.
(b) Recommended Days of Re		
		ot Required
(c) Resurvey		
(c) Resurvey (d) Excess	:\$	

## **Spark Car Care**

### ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

#### Spare Parts

Vehicle No		SMM4972X	Case Owner		0
Make & Model	:	HYUNDAI AD AVANTE 1.6	Year Manufacture		2019
Chassis No	:	KMHD841CMKU910305	Engine No	·	G4FGKU146835
Sales Order	•	H	Supplier		
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper	1	11100	THE	Trice	3/14	Surveyor
2	Front bumper fog lamp RH	1					
_	Front bumper grille RH	1					
	Front bumper side retainer RH	1					
	Front bumper upper bracket RH	1					
	Front bumper clip	1					
	RH headlamp	1					
	0	1					
	0	1					
_	0	1					
	0	1					
	0	1					
	0	1					
	0	0					
	0	0					
	0	0					
	0	0					
_	0	0					
_	0	0					
_	0	0					
	0	0					
_	0	0					
	0	0					
-	0	0					
	0	0					
	0	0					
_	0	0					
	0	0					
_	0	0					1
-	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

## **Spark Car Care**

# ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

### <u>Labour</u>

/ehicle No.	3	SMM4972X	Case Owner		0	
Make & Model		JNDAI AD AVANTE 1.6 GLS A	Year of Manufacture	(i)	2019	

Labour Description	Esimated Price	Adjusted Price
	\$120.00	
and replace damaged parts.		
To check wiring functions and focus headlamps.	\$40.00	
To putty, apply primer & spray-paint the RH front fender, front	\$500.00	
bumper and affected areas.		
To apply rust-proofing on repaired/replaced panels.	\$50.00	
	Labour charges to repair and panel beat the RH front fender and replace damaged parts.  To check wiring functions and focus headlamps.  To putty, apply primer & spray-paint the RH front fender, front bumper and affected areas.	Labour charges to repair and panel beat the RH front fender and replace damaged parts.  To check wiring functions and focus headlamps.  \$40.00  To putty, apply primer & spray-paint the RH front fender, front bumper and affected areas.

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.