



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101763

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 18/03/2021
Reference CC6/FCI20014241/Aes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLB 2596G
Insured Veh. SHA 1049D
Claim No. D20005129MFSH
Policy No. D-18088936MFSH
Accident Date 12/12/2020
Inspection Date 16/12/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20014241/Aes3q2 Date: 18/03/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1049D	Veh. Inspected	SLB 2596G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D20005129MFSH	Excess (\$)	0.00	
Assign From	VIC	Assign Date	16/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET ORLANDO	c.c	1362	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KL1YA7589GK337477	Colour	WHITE	
Odometer	70772 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/12/2020	Inspection Date	16/12/2020	
Survey held at	POLYMATH GARAGE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-02 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 2596G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,330.00	1,330.00
2	REAR BUMPER SIDE HOLDER @\$55.00	NECESSARY	110.00	110.00
1	REAR BUMPER LOWER GARNISH (BLACK)	DEFORMED	493.00	493.00
1	REAR BUMPER LOWER GARNISH (SILVER)	DEFORMED	223.00	223.00
1	REAR BUMPER TOP COVER	CRACKED	166.00	166.00
1	REAR BUMPER LAMP	CRACKED	307.00	307.00
1	REAR BUMPER REINFORCEMENT	BENT	863.00	863.00
2	REAR BUMPER REFLECTOR @\$140.00	N/S CRACKED	280.00	140.00
1	REAR BUMPER CENTRE BRACKET	CRACKED	148.00	148.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	776.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	186.00	-
4	REVERSE SENSOR @\$215.00	DAMAGED (2 PCS ONLY)	860.00	430.00
4	REVERSE SENSOR HOLDER @\$10.00	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-578.20	-425.00
			5,203.80	3,825.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER TOP COVER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR BUMPER CENTRE BRACKET RIVETS (SN)	NECESSARY	30.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	SET FRONT GRILLE CLIPS (SN)	NOT NECESSARY	30.00	-
			190.00	80.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	300.00
	SPRAY PAINTING .		600.00	250.00
	WIRING .		50.00	30.00
	TO SPRAY TUFF COAT.	NOT NECESSARY	150.00	-

Report Ref No. CC6/FCI20014241/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE UPHOLSTERY .	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR .		100.00	60.00
			1,850.00	640.00
GRAND TOTAL			7,243.80	4,545.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC6/FCI20014241/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 2596G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 2596G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 2596G

RE-INSPECTION

