



CYCLE & CARRIAGE

AIG-OD CLAIM
Survey: 25/03/21
LKK-STEVE

VEHICLE NO : SMS 3376 S

MODEL : MIT/SPACE STAR 1.2 CVT

WIP : 61018

Material	:	\$	<u>2,447.06</u>
Labour	:	\$	<u>1,545.00</u>
Sub-Total	:	\$	<u>3,992.06</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>3,392.06</u>
GST 7%	:	\$	<u>237.44</u>
Grand Total	:	\$	<u>3,629.50</u>
Finalise By/Date : <u>LARRY ON 09/04/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk.end)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 25/03/2021	<table border="1"> <tr><td>Cust No/Name</td><td>/LIM EILYN</td></tr> <tr><td>Reg No/Reg Date</td><td>SMS3376S / 21/02/2020</td></tr> <tr><td>Date In/Mileage</td><td>25/03/2021/ 9735</td></tr> <tr><td>Chassis/Package</td><td>MMBXTA03ALH000277 /#</td></tr> <tr><td>Engine No</td><td>3A92UJB8609</td></tr> <tr><td>Make/Model</td><td>MIT/20MY SPACE STAR 1.2 CVT 2WD</td></tr> <tr><td>Colour/Trim</td><td>P01 RED METALLIC / BK BLACK</td></tr> </table>	Cust No/Name	/LIM EILYN	Reg No/Reg Date	SMS3376S / 21/02/2020	Date In/Mileage	25/03/2021/ 9735	Chassis/Package	MMBXTA03ALH000277 /#	Engine No	3A92UJB8609	Make/Model	MIT/20MY SPACE STAR 1.2 CVT 2WD	Colour/Trim	P01 RED METALLIC / BK BLACK
Cust No/Name	/LIM EILYN														
Reg No/Reg Date	SMS3376S / 21/02/2020														
Date In/Mileage	25/03/2021/ 9735														
Chassis/Package	MMBXTA03ALH000277 /#														
Engine No	3A92UJB8609														
Make/Model	MIT/20MY SPACE STAR 1.2 CVT 2WD														
Colour/Trim	P01 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	09/04/2021/ 09:13	BLE	884 / Lauro Songcuan	61018

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER & LH FRONT FENDER				675.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER & LH FRONT FENDER				700.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X EXC EXCESS				-600.00
X FACE,FR BUMPER ✓	1.00	751.00	23.00	578.27 ✓
X CLIP,FR BUMPER ✓	5.00	4.00	23.00	15.40 ✓
X HEADLAMP ASSY,LH ?	1.00	1842.00	23.00	1418.34 ?
X FENDER,FR LH	1.00	435.00	23.00	334.95 X
X PANEL,AIR GUIDE	1.00	100.00	23.00	77.00 X
X RIVET,FR BUMPER	6.00	5.00	23.00	23.10 X
Z TEXT				
A OD CLAIM - AIG SURVEY: STEVE (LKK) 25.03.2021 DOA: 03.10.2020 04 DAYS				

* - change price

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,447.06	Nett	3,392.06
Labour	1,525.00	7% GST on	237.44
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	3,629.50
Sundry/Others	-580.00		
Total(w/o GST)	3,392.06		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMS 3376 S

<u>Materials</u>		<u>Cost \$</u>
1	Fender, FR LH	435.00 / DD
2	Panel, Air Guide	100.00 / BR
3	Rivet, FR Bumper (6 pcs)	30.00 / REC
		<u>565.00</u>
23% Discount		<u>129.95</u>
		435.05
7% GST		<u>30.45</u>
Total		<u>465.50</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SM533765WIP: 61018

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	FR LEADER, LH	? / SUPP		OK	Steve 26/3/21
2	FRT AIR GUIDE	? / SUPP		OK	
3	HEADLAMP LH	? / SUPP		OK	
4	RIVET (6PCS)	? / SUPP		OK	Steve 31/3/21
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: SPACE STARSURVEYOR: STEVE

All DTCS

For No. 3M1333F63

Before using MUT-3, you will be checked all the sound 2021.04.01

Setting	
Item	Information
M.U.T.-3 Version	SEW20121-00
V.C.I. Version	B179
Vehicle Information	A03A 2020MY

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	ETACS_83040600		No DTCs	
AT/CVT/A-MT/TC-SST	ETACS_83040600		No DTCs	
4WS/Electric Power Steering	ETACS_83040600		No DTCs	
ABS/ASC/ASTC/WSS	ETACS_83040600		No DTCs	
SRS-AIR BAG	ETACS_83040600	B1431 B1421	FL side ABG squib open FR side ABG squib open	Stored Stored
Air Conditioner	ETACS_83040600		No DTCs	
ETACS	ETACS_83040600	B1707	Flasher open	Active
Meter	ETACS_83040600		No DTCs	
Steering Angle Sensor	ETACS_83040600		Non-target System	
LIN	ETACS_83040600		Non-target System	
KOS/OSS/IMMO/Keyless (without KOS)	ETACS_83040600	B1707	Flasher open	Active

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20121-00
V.C.I. Version		B179
Vehicle Information		A03A 2020MY

For no. SPAS33F63

After use, must be use unit to test all the found

to do Dan

as test drive check condition

to by Q.C

</					