



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /GOH KOK SUA Reg No/Reg Date SLH7433D / 17/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5648996 Engine No G4FGGH637993 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	22/12/2020/ 08:41		442 / Cocolu	26105		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT SUPPORT PANEL							800.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER,							350.00
M SUNDRY FRT NUMBER PLATE WITH FRAME							50.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 RENEW REAR BUMPER, BOOTLID, REAR LAMP HOUSING RH & LH, REAR END PANEL							5600.00
2 REAR COMPARTMENT, REPAIR REAR CHASSIS RH & LH, REAR FENDER RH							
E PNT88000 REMOVE & INSTALL REAR SEATS AND CARPET							200.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS							200.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, REAR LAMP HOUSING RH & LH							2800.00
2 REAR FENDER RH, REAR COMPARTMENT, REAR CHASSIS RH & LH							
E PNT88000 CONDUCT CELLEBENCH TO STRAIGHTEN REAR CHASSIS							1000.00
E PNT88000 REMOVE & INSTALL FRT PARKING SENSOR							60.00
E PNT88000 REMOVE & INSTALL REAR PARKING SENSOR							60.00
M SUNDRY C&C LOGO							40.00
M SUNDRY APPLY SEALANT FOR ACCIDNET PORTION							100.00
M SUNDRY Sundry							20.00
Confirm & accepted by							
Authorized signatory and company stamp							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /GOH KOK SUA Reg No/Reg Date SLH7433D / 17/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5648996 Engine No G4FEGGH637993 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/12/2020/ 08:41		442 / CocoLu	26105			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GRILLE ASSY-RADIATOR	✓	BT		1.00	328.00	20.00	262.40
M	COVER-FR BUMPER	X R			1.00	633.00	20.00	506.40
M	MOULDING-FRT BPR LICENSE PLATE	✓	BR		1.00	18.00	20.00	14.40
M	MOULDING-FRONT BUMPER A/INTAKE	✓	(low grL) - BR		1.00	91.00	20.00	72.80
M	ABSORBER-FRONT BUMPER ENERGY	✓			1.00	84.00	20.00	67.20
M	RAIL ASSY-FR BUMPER	✓			1.00	496.00	20.00	396.80
M	ULTRASONIC SENSOR ASSY-P.A.S	✓			1.00	177.00	20.00	141.60
M	ORNAMENT-KIA NO.115	✓	NC		1.00	32.00	20.00	25.60
M	LOGO ASSY-KIA SUB	✓	NC		1.00	37.00	20.00	29.60
M	EMBLEM-CERATO	✓	NC		1.00	35.00	20.00	28.00
M	COVER-RR BUMPER	✓	BR		1.00	688.00	20.00	550.40
M	COVER-RR BUMPER,CTR	✓	BR		1.00	315.00	20.00	252.00
M	ANTENNA ASSY-SMARTKEY	✓			1.00	69.00	20.00	55.20
M	BEAM-RR BUMPER	✓	BR		1.00	318.00	20.00	254.40
M	BRACKET-RR BEAM LWR MTG	✓	BT		1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM LWR,CTR	✓	BT		1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM UPR MTG	✓	BR		1.00	3.00	20.00	2.40
M	BRACKET-RR BEAM UPR MTG,RH	✓	BR		1.00	3.00	20.00	2.40
M	STAY-RR BUMPER LH	✓	BT		1.00	120.00	20.00	96.00
M	STAY-RR BUMPER RH	✓	BT		1.00	120.00	20.00	96.00
M	BRACKET-RR BUMPER SIDE MTG,LH	✓	BT		1.00	29.00	20.00	23.20
M	BRACKET-RR BUMPER SIDE MTG,RH	✓	BT		1.00	29.00	20.00	23.20
M	GUARD-BUMPER REAR,RH	✓	MIS		1.00	17.00	20.00	13.60
M	WIRING HARNESS-BWS EXT	✓	TN		1.00	216.00	20.00	172.80
M	ULTRASONIC SENSOR ASSY-P.A.S	✓	BR		1.00	177.00	20.00	141.60
M	ULTRASONIC SENSOR ASSY-P.A.S	✓	BR		1.00	177.00	20.00	141.60
M	ULTRASONIC SENSOR ASSY-P.A.S	✓	BR		1.00	177.00	20.00	141.60
M	ULTRASONIC SENSOR ASSY-P.A.S	✓			1.00	177.00	20.00	141.60
M	PANEL ASSY-TRUNK LID	✓	BT		1.00	1365.00	20.00	1092.00
M	HINGE ASSY-TRUNK LID,LH	✓			1.00	68.00	20.00	54.40
M	HINGE ASSY-TRUNK LID,RH	✓			1.00	68.00	20.00	54.40
M	PANEL ASSY-RR COMB LAMP HSG,LH	✓	BT (photo)		1.00	166.00	20.00	132.80
M	PANEL ASSY-RR COMB LAMP HSG,RH	✓			1.00	166.00	20.00	132.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /GOH KOK SUA Reg No/Reg Date SLH7433D / 17/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5648996 Engine No G4FGGH637993 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/12/2020/ 08:41		442 / CocoLu	26105

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL ASSY-BACK <i>✓</i>	1.00	324.00	20.00	259.20
M PNL ASSY-RR FLOOR RR COMPLETE <i>✓</i>	1.00	602.00	20.00	481.60
M TRIM-TRANSVERSE RR <i>✓</i>	1.00	58.00	20.00	46.40
M TRIM ASSY-LUGGAGE SIDE RH <i>✓</i>	1.00	161.00	20.00	128.80
M MAT ASSY-LUGGAGE COVERING <i>✓</i>	1.00	159.00	20.00	127.20
M TRIM ASSY-LUGGAGE SIDE LH <i>✓</i>	1.00	161.00	20.00	128.80
M LAMP ASSY-REAR COMB INSIDE, RH <i>✓</i>	1.00	710.00	20.00	568.00
M LAMP ASSY-REAR COMB INSIDE, LH <i>✓</i>	1.00	710.00	20.00	568.00
M LAMP ASSY-REAR COMBINATION, RH <i>✓</i>	1.00	788.00	20.00	630.40
M LAMP ASSY-REAR COMBINATION, LH <i>✓</i>	1.00	788.00	20.00	630.40
M LAMP ASSY-HEAD, RH <i>✓</i>	1.00	1707.00	20.00	1365.60
M LAMP ASSY-HEAD, LH <i>✓</i>	1.00	1707.00	20.00	1365.60

Estimate

Steve (LKK)
22/12/20, 11:30am
00- NM AutL
EXCESS - ?
P/P
Ry Bel sy
16 dys

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed

Confirmation accepted by repairer and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

	Nett	22,857.20
7% GST on	22857.20	1600.00
Total Payable		24,457.20

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.