

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/GOH KOK SUA
Ltd.	Reg No/Reg Date	SLH7433D / 17/11/201
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0
78 SHENTON WAY #08-16	Chassis No	KNAFZ411MH5648996
AIG BUILDING SINGAPORE 079120	Engine No	G4FGGH637993
Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A SX HADQ
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	22/12/2020/ 08:41		442 / CocoLu		26105		
		Description of Good	s / Services		Qty	Unit Price	Disc%	Amount
E PNT88000								800.00
	T BUMPER,	, FRT SUPPORT PANEL						250.00
E PNT98000	FAD /	TOT DUMBED						350.00
M SUNDRY	INI FOR I	FRT BUMPER,					İ	50.00
	FR PLATE	WITH FRAME						00100
A 90000001	LK I LIUL	WITH TRUIC						30.00
	RING & EI	ECTRICAL SYSTEM						
A 10028901								120.00
		GNOSTIC CHECK USING	HI-SCAN PRO) TEST				
USING HI	-SCAN PRO) TEST	_ Л.		Л			5600.00
E PNT88000	AD DUMBET	R, BOOTLID, REAR LAM	PHOUST NO.	OH I H DEAD ENT	DANE!	7)		3000.00
RENEW KE	AR BUMPE PARTMENT	REPAIR REAR CHASSI	S BH & I H.	REAR FENDER RH		7		
E PNT88000	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	KEIMIK KEMIK GIMGO	5 a C, , [- U -			200.00
REMOVE &	INSTALL	REAR SEATS AND CARP	ET					
E PNT88000								200.00
	INSTALL	REAR COMPARTMENT TR	IMS					2000 00
E PNT98000	INT COD I	DEAD DUMBED DEAD EN	D DAMEL DE	AD LAMB HOUSTNE DI	⊔ 0. IL i			2800.00
		REAR BUMPER, REAR EN REAR COMPARTMENT, RE			n & Ln			
E PNT88000	DEN KII, I	CLAR COM ARTHLING RE	AR CHAJJIJ	KII & EII				1000.00
	CELLEBEN	CH TO STRAIGHTEN REA	R CHASSIS					
E PNT88000								60.00
	INSTALL	FRT PARKING SENSOR						60.00
E PNT88000	TNCTALL	REAR PARKING SENSOR						60.00
M SUNDRY	INSTALL	KEAK PAKKING SENSUK						40.00
C&C LOGO								
M SUNDRY								100.00
APPLY SE	ALANT FOI	R ACCIDNET PORTION						
M SUNDRY								20.00
Sundry								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/GOH KOK SUA		
Ltd.	Reg No/Reg Date	SLH7433D / 17/11/201		
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0		
78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120	Chassis No	KNAFZ411MH5648996		
	Engine No	G4FGGH637993		
Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A SX HADQ		
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	22/12/2020/ 08:41		442 / CocoLu		26105		
		Description of Good	s / Services		Qty	Unit Price	Disc%	Amount
M GRILLE AS	SSY-RADIA	TOR			1.00	328.00		262.40
M COVER-FR					1.00	633.00	20.00	506.40
		LICENSE PLATE			1.00		20.00	14.40
		IMPER A/INTAKE			1.00		20.00	72.80
		IMPER ENERGY			1.00		20.00	67.20
M RAIL ASS'	/-FR BUMF	PER			1.00	496.00		396.80
		R ASSY-P.A.S			1.00	177.00		141.60
M ORNAMENT	-KIA NO.1	.15			1.00		20.00	25.60
M LOGO ASS'					1.00	37.00	20.00	29.60
M EMBLEM-C					1.00		20.00	28.00
M COVER-RR			[1.00	688.00	20.00	550.40
M COVER-RR		CTR	20	10000	1.90	315.00		252.00
M ANTENNA A		RTKEY	5		1.00	69.00	20.00	55.20
M BEAM-RR			O) (4)	ima	4.00	318.00	20.00	254.40
M BRACKET-I	RR BEAM L				1.00		20.00	4.00
M BRACKET-I	RR BEAM L	.WR,CTR			1.00		20.00	4.00
M BRACKET-I	RR BEAM L	JPR MTG			1.00		20.00	2.40
M BRACKET-I	RR BEAM L	JPR MTG,RH			1.00		20.00	2.40
M STAY-RR I	BUMPER LE	1			1.00	120.00		96.00
M STAY-RR I	BUMPER RE	 			1.00	120.00		96.00
M BRACKET-I	RR BUMPER	R SIDE MTG,LH			1.00		20.00	23.20
M BRACKET-I	RR BUMPER	R SIDE MTG,RH			1.00		20.00	23.20
M GUARD-BU	MPER REAF	R,RH			1.00		20.00	13.60
M WIRING HA	ARNESS-BV	VS EXT			1.00	216.00		172.80
M ULTRASON	IC SENSOR	R ASSY-P.A.S			1.00	177.00		141.60
M ULTRASON	IC SENSOR	R ASSY-P.A.S			1.00	177.00		141.60
M ULTRASON	IC SENSOR	R ASSY-P.A.S			1.00	177.00		141.60
M ULTRASON	IC SENSOF	R ASSY-P.A.S			1.00	177.00		141.60
M PANEL AS:	SY-TRUNK	LID			1.00	1365.00		1092.00
M HINGE AS	SY-TRUNK	LID, LH			1.00		20.00	54.40
M HINGE AS:					1.00		20.00	54.40
		MB LAMP HSG,LH			1.00	166.00		132.80
		MB LAMP HSG,RH			1.00	166.00	20.00	132.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

Authorized signatory and company stamp

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/GOH KOK SUA		
Ltd.	Reg No/Reg Date	SLH7433D / 17/11/201		
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0		
78 SHENTON WAY #08-16	Chassis No	KNAFZ411MH5648996		
AIG BUILDING SINGAPORE 079120	Engine No	G4FGGH637993		
Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A SX HADQ		
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK		

1 4 4 0 0 0 0 0	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	22/12/2020/ 08:41		442 / CocoLu		26105		
		Description of Good	s / Services		Qty	Unit Price		Amount
M TRIM-TRAM TRIM ASSYM MAT ASSYM TRIM ASS M LAMP ASS M LAMP ASS M LAMP ASS M LAMP ASS M LAMP ASS M LAMP ASS	Y-RR FLOOF ANSVERSE F SY-LUGGAGE Y-LUGGAGE SY-LUGGAGE SY-REAR CC SY-REAR CC SY-REAR CC	R RR COMPLETE RR E SIDE RH COVERING E SIDE LH DMB INSIDE,RH DMB INSIDE,LH DMBINATION,RH DMBINATION,LH		ma	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	324.00 602.00	20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00	259.20 481.60 46.40 128.80 127.20 128.80 568.00 630.40 630.40 1365.60
								

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

24,457.20

Total Payable