

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III20014244/T1GA3Q2
Date: 17/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SHA2344U	Insured Vehicle No :	GBG8480J
Date of Loss:	20/12/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2344U		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B84935
Reg. Date:	07/01/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU703077820
Colour:	Blue	Odometer:	292546 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,740.62	750.40	3,990.22	84.17
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	930.00	780.00	150.00	16.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,681.62	1,541.40	4,140.22	72.87
+ GST 7.00/7.00% (S\$)	397.71	107.90	289.81	72.87

Nett Amount (S\$)	6,079.33	1,649.30	4,430.03	72.87
+ Loss of Use (4.0 x S\$40.00/day) (S\$)		160.00		
+ Car Rental (4.0 x S\$129.68/day) (S\$)		518.72		
(S\$)		2,328.02		
Liabe Amount (90.00%) (S\$)		2,095.22		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,102.71		
Global Sum Settlement (S\$)		2,000.00		

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2021)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2344U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	499.90 FL	*499.90 FL
2	1		*FRT BUMPER UPR BRKT RH	Cracked	82.30 FL	*82.30 FL
3	1		*FRT FENDER RH	Repair	945.30 FL	*- FL
4	1		*FRT FENDER SHIELD RH	Deformed	198.50 FL	*198.50 FL
5	1		*FRT FENDER HYDRID RH	Necessary	86.50 FL	*86.50 FL
6	1		*HEADLAMP RH	Not Necessary	3,455.00 FL	*- FL
7	1		*FRT FENDER ADVERTISEMENT STICKER RH	Necessary	100.00 FS	*100.00 FS
8	1		*FOGLAMP RH	Not Necessary	920.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,287.50	967.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,546.88	216.80
Total Parts (\$\$)	4,740.62	750.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP CASE (INSURER)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING	New	500.00	400.00
3	CHECK LIGHTINGS	New	40.00	30.00
4	TUFF KOTE	New	40.00	30.00
Gross Labour Cost (S\$)			930.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >