

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20014248/QQD3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SJM2975L

Insured Vehicle No : GBB6468K

Date of Loss: 19/12/2020

Nature of Claim:

TP

Claim No: CDMCG20001962

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM2975L

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FC8H014567

Reg. Date: 29/12/2008 (Man. Year: 2008)

Chassis No: KNAFE227395637852

Colour: White

Odometer: 161045 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/40 ZR17

Rear Tyre Size:

215/40 ZR17

Front Left Side: Firenza 6 mm

Rear Left Side:

Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side:

Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,300.00	1,066.50	3,233.50	75.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,650.00	970.00	4,680.00	82.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,950.00	2,036.50	7,913.50	79.53
Approved Total (Overridden) (\$\$)		1,650.00		
Nett Amount (\$\$)	9,950.00	1,650.00	8,300.00	83.42

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 22/12/2020 Inspected At:

Auburn Auto Pte Ltd (HQ)
176 SIN MING DRIVE, #04-18 SIN
MING AUTOCARE
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2021)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM2975L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER CLIP RIGHT	Serviceable	150.00 F	*- FL
2	1		*BUMPER STRIP	Serviceable	200.00 F	*- FL
3	1		*FRONT RIGHT RIM	Scratched	200.00 F	*200.00 FL
4	1		*FRONT RIGHT DOOR SPEAKER	Serviceable	250.00 F	*- FL
5	1		*RIGHT SIDE FENDER	Dented	250.00 F	*250.00 FL
6	1		*UNDER TRAY COVER	Serviceable	350.00 F	*- FL
7	1		*CONDENSER	Serviceable	450.00 F	*- FL
8	1		*RADIATOR	Serviceable	450.00 F	*- FL
9	1		*FRONT RIGHT DOOR REPLACE	Dented	2,000.00 F	*735.00 FL
					Sub Total (\$\$)	4,300.00 1,185.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 118.50
					Total Parts (\$\$)	4,300.00 1,066.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECKING OF WIRING,LIGHTING AND RESETTING	New	850.00	30.00
2	REMOVE AND REFIT REAR UNDERCARRIAGE	New	500.00	0.00
3	WHEEL ALIGNMENT	New	300.00	0.00
4	REMOVE AND REPLACE DAMAGED PARTS	New	1,000.00	0.00
5	APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	800.00	40.00
6	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIRS INCLUDING CUT AND WELD,REALIGN BODY STRUCTURE	New	1,200.00	450.00
7	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	450.00
Gross Labour Cost (\$)			5,650.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >