

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Kia

Cerato

Vehicle Number : SJM2975L

Quantity	Description	Repairer's Estimate
1	Bumper Clip Right <i>X SVC</i>	\$150
1	Bumper Strip <i>X SVC</i>	\$200
1	Front Right Rim <i>/ SCR</i>	\$200 <i>/</i>
1	Front Right Door Speaker <i>X SVC</i>	\$250
1	Right Side Fender <i>/ DN</i>	\$250 <i>/</i>
1	Under Tray Cover <i>X SVC</i>	\$350
1	Condenser <i>X SVC</i>	\$450
1	Radiator <i>X SVC</i>	\$450
1	Front Right Door Replace <i>/ DN</i>	<del>\$2,000</del> <i>735</i>
		<i>-10%</i>
	<b>LABOUR &amp; MISC</b>	
1	Checking of wiring, lighting and resetting	\$850 <i>30</i>
1	Remove and refit rear undercarriage	\$500 <i>X</i>
1	Wheel alignment	\$300 <i>X</i>
1	Remove and replace damaged parts	\$1,000 <i>X</i>
1	Apply undercoating on repaired and replaced panel	\$800 <i>40</i>
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200 <i>450</i>
1	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000 <i>450</i>
	<i>Repair day 3 days</i>	
	<b>Total Repair Cost :</b>	<b>\$9,950</b>

*1,185.00*  
*-10%*  
*1,066.50*

*970*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*21s*  
*\$1,650*  
*3 days*

*1,066.50*  
*970*  
*2,036.50*  
*-20%*  
*1,629.20*