

REPAIR ESTIMATE

JM

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305439662
 REGN NO : SHA8656E
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 14.07.2016
 DATE/TIME IN : 17.12.2020 12:45
 ACCIDENT DATE : 17.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER COVER+	1	1,052.20	20.00	841.76	ole	
0002 04-01-0103-0573-A	I40VC PANEL-FENDER RH+	1	663.00	20.00	530.40	bt	
0003 04-01-0103-0782-A	I40VC LAMP ASSY-HEAD RH#	1	1,800.00	20.00	1,440.00	X nn	
0004 04-01-0103-0640-G	BRACKET-FR BUMPER SIDE RH	1	24.60	20.00	19.68	X nn	1932.40
0005 04-01-0103-0638-G	BRKT ASSY-FR BPR UPR SIDE	1	22.40	20.00	17.92	X nn	20% - 1545.92.
0006 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	wt	129.60
supp Frt RH tyre 216 ant 60% - 129.60.							1675.52.
SUB-TOTAL :							3,023.52

JOB NATURE

0000 PB	PANEL BEATING	600.00	420.	
0001 SP	SPRAYPAINT CHARGE	500.00	400	
0002 17-01	CHECK ALL LIGHTING	50.00	30	880.
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30	2555.52.
SUB-TOTAL :				1,200.00

Tanphin 9749 5749
 'wp' 18/12/20 @ 1pm
 4/5 Resurvey after repair
 Tanphin @ 11h30am
 2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: