

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: SFH5233Z
Repairer Reference: 038352
Date calculated: 23/12/2020 2:34 PM

Full Report
Registration: SFH5233Z
Printed: 23/12/2020 2:40 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	SFH5233Z	Date of Incident:	17/12/20
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: HONDA
Model: CIVIC (FD)
Sub Model: BASE MODEL
Model Sheet Number: 35 48 01
Registration: SFH5233Z
VIN number:
Odometer: 0

Model Specs

2.0 LTR 114 KW


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All
Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R FRONT NUMBER PLATE		1.0	4.20
0258	FRT NO PLATE REINF CHECK			
0283	FRONT BUMPER CHECK			
0318	R/F OUT BUMPER BRKT CHECK			
0343	FRONT BUMPER SPOILER CHECK			
0345	L/BUMPER COVER CHECK			
0412	GRILLE CHECK			
0841	L/WHEELHOUSE SHELL CHECK			
7920	ENGINE BLOCK CHECK			
Labour Cost			Hrs	WU
Panel / Mechanical Labour			0.10	1.0
Total of Labour				4.20

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	
				WU	Price SGD
0257	FRONT NUMBER PLATE		Original		25.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				25.00
u: Used parts	Total				25.00

Final Calculation

	SGD	SGD
Parts	25.00	
Total Parts		25.00
Labour Time Base 10 WU/h		
Total 1.0 WU X 42.00 SGD/h	4.20	
Total of Labour		4.20
Repair Cost Excludes GST		29.20
GST (+7.0%)		2.04
Repair Cost Included GST		31.24

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.