

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Dieg Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 2500

(Client's Record)

Make of Veh: _____

(Policy Condition)

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 22k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6-7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 05/23 Person Contacted: _____ Vehicle: IN/OUT

Veh No: SFH 5233 Z Yr Regn: 06, 08.

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Honda Civic c.c. 1998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SFHMF0254085201386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 215/45ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Tour Road

Front/ Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 17/12/20 D.O.I. 22/12/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

veh near to a pool of water Follow by engine

The U/C / Chassis frame / Body Structure affected due to collision.

Stored.

Date / Time	Action / Instruction
<u>1</u>	<u>Fit parts to Modified air hose to bottom, veh unable to start. To do investigation on consistency.</u>
	<u>SUBMIT PRELI REPORT.</u>
	<u>BLEACH OF CONTRACT, CASH JOB</u>

Date/Time, File Pass to? : Preli. Report : Final Report

Date/Time, File Return to? _____

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	_____ \$ - RS. _____ \$
Fixtures:	_____ \$
Others:	_____ \$

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ 500)

: Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



Insurer Reference: SFH5233Z
Repairer Reference: 038352
Date calculated: 21/12/2020 1:23 PM

Full Report
Registration: SFH5233Z
Printed: 21/12/2020 1:23 PM

Summary Information

Claim		Work Provider:	China Taiping Insurance
Location:	Singapore (SG)		(Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:	SFH5233Z	Date of Incident:	17/12/20
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: HONDA
Model: CIVIC (FD)
Sub Model: BASE MODEL
Model Sheet Number: 35 48 01
Registration: SFH5233Z
VIN number:
Odometer: 0
Model Specs
2.0 LTR 114 KW

Not Authorized

Ex B 2501

LICK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer
Signature:
Date:

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All
Underbody



Labour

Code	Description	Time Base 10 WU/h		Price = 42.00 SGD/h	
		WU	Price SGD	WU	Price SGD
11000-RRA) NO NUMBER	RENEW PARTIAL ENGINE (ENGINE REMOVED) R + R ENGINE AND GEARBOX INCLUDES: R + R AIR FILTER CPL, BATTERY, BATTERY BRACKET, FRONT AXLE CROSSMEMBER, ENGINE PROTECTION, FRONT EXHAUST AND DRIVE SHAFTS	83.0	348.60	71.0	298.20
71101-SNB	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER CPL AND R + R RADIATOR GRILLE.	6.0	25.20		
33151-SNB)	R + R LEFT HEADLAMP UNIT	4.0	16.80		
33101-SNB)	R + R RIGHT HEADLAMP UNIT	4.0	16.80		
NO NUMBER	ADJUST HEADLAMP	1.0	4.20		
74151-SNG	R + R LEFT FRONT WHEELHOUSE INSERT	3.0	12.60		
Labour Cost		Hrs	WU		
Panel / Mechanical Labour		17.20	172.0	722.40	
Total of Labour				722.40	

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R		10.0	

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	39.09

Labour Cost - Paint

	Factor	42.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			10.0	
	Preparation Comp. Work Plastic		0.70	7.0	29.40
	Total	10 WU/h	1.70	17.0	71.40

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	39.09
Material-constant Plastic	16.20
Total	55.29

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
7920	ENGINE BLOCK	11000RRAA00	Used		3,000.00 ?

Code	Description	Part Number	Part Source	Price SGD
0283	FRONT BUMPER	71101SNLQ90ZZ	Original	210.00
0343	FRONT BUMPER SPOILER	71110SNB000	Original	90.00
0257	FRONT NUMBER PLATE		Original	25.00
0258	FRT NO PLATE REINF		Original	20.00
0412	GRILLE	71121SNLT01	Original	45.00
0345	L/BUMPER COVER	71109SNB000	Original	18.00
0561	L/F HEADLAMP CPL	33151SNBT03	Original	300.00
0317	L/F OUT BUMPER BRKT	71198SNB003	Original	30.00
0841	L/WHEELHOUSE SHELL	74151SNAA10	Original	90.00
0562	R/F HEADLAMP CPL	33101SNBT03	Original	300.00
0318	R/F OUT BUMPER BRKT	71193SNB003	Original	30.00
0410	RADIATOR GRILLE TRIM	71122SNLT01	Original	75.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	4,233.00
Total	4,233.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	4,233.00	4,233.00
Labour Time Base 10 WU/h		
Total 172.0 WU X 42.00 SGD/h	722.40	722.40
Total of Labour		
Paint Work Time Base 10 WU/h		
Labour Cost 17.0 WU X 42.00 SGD/h	71.40	
Material Cost	55.29	
Total Paint Including Material		126.69
Repair Cost Excludes GST		5,082.09
GST (+7.0%)		355.75
Repair Cost Included GST		5,437.84

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/12/2020 15:43 (SGT)
Date of Accident	17/12/2020 15:20 (SGT)
Exact Location of Accident	Muslim Cemetery Path 17, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFH5233Z
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	MOHAMMED NIZZAAR BIN ABDUL NAZZEER
NRIC No	SXXXX797D
Email Address	BLACK.NIZZAAR@GMAIL.COM
Mobile Phone No	(Phone) +65-87504580
Alternative Phone No	+65-87424182

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Civic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car


INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00116882000
Cover Note Number	-

DRIVER

Name of Driver	MOHAMMED NIZZAAR BIN ABDUL NAZZEER
NRIC No	SXXXX797D
Date Of Birth	24/02/1985
Occupation	Outdoor

Accident report SD0820CJ0001



A. SFH52332

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17th December 2020 at about 1520hrs, I was going for a funeral at Puscara Abadi. That was when I drove down the slope of Muslim Cemetery Path 17 and went into a big puddle of water when suddenly my car engine died. The car roll upward a little up the slope before I attempt to start the engine again. But the engine could not be started. As it was raining heavily I stayed in the car with my hazard light on. Being in the car, I thought it was battery issue so I called up the battery guy using video call to seek his advice. He told me that this is not battery issue that he asked me to call for towing. So I called for towing. My car was later towed to my workshop at My Car Consultant.

Do not take while waiting for towing to come, after about 45min, the rain started to lessen so I got out of the car to open my back bonnet. This is when I found my front number plate on the ground slightly behind my car. So I pick it up and ^{went} to the front of my car which to my horror seem badly damage due to the impact against the big puddle of water.

There is no injury and no police report made.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Link to OneMotoring
Require PARF/COE Rebate for Registered Vehicle
Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC
797D

Owner ID:
Vehicle Details

Vehicle No.:

SFH5233Z

Vehicle to be Exported:

Yes

Intended Deregistration Date:

25 Dec 2020

Vehicle Make:

HONDA

Vehicle Model:

CIVIC 2.0L M

Primary Colour:

White

Manufacturing Year:

2008

Engine No.:

K20Z23501586

Chassis No.:

JHMF25408S201586

Maximum Power Output:

114.0 kW (152 bhp)

Open Market Value:

\$21,829.00

Original Registration Date:

16 Jun 2008

First Registration Date:

16 Jun 2008

Transfer Count:

5

Actual ARF Paid:

\$21,829.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

31 May 2023

COE Category:

B - Car (1601cc & above)

COE Period(Years):

5

PQP Paid:

\$19,356.00

COE Rebate Amount:

\$9,417.00

Total Rebate Amount:

\$9,417.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Dec 2020

OK