



Final Report

Estimate No. : **b1 56985**
Date Estimated : **22/12/2020**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -
Ang Eng Joo
182 Bukit Batok West Ave 8
#08-147

Singapore 650182

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMJ9548X	WBAJA12050BJ209	26/03/2019	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace bumper front panel and make good front right side panel	1,700.00	0.00	1,700.00
To spray paint bumper front panel and front right side panel.	1,730.00	0.00	1,730.00
To replace right headlight and reprogramming	408.00	0.00	408.00
To transfer PDC assembly parts and connect to new bumper.	150.00	0.00	150.00
To check electrical wiring system at the front section.	150.00	0.00	150.00
Sundries	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,384.80	1.00	0.00	1,384.80
RH HEADLIGHT LED AHL HIGH (ICON LIG	4,879.55	1.00	0.00	4,879.55

#

SUPPLEMENTARY ITEMS

Total Labour :	4,288.00
Total Parts :	6,264.35
Total Labour & Parts :	10,552.35
Deduction for Excess :	750.00
Total Repair Costs less Excess:	9,802.35
GST @7%:	686.16
Grand Total :	10,488.51