



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20014260/Uvd3q2	
			Date: 05/01/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMR 7220L	Veh. Inspected	SMP 4981D
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003750/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/12/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA PRIUS PLUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTDZS3EU00J049630	Colour	GREY
	Odometer	126842 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	205/60 R16	PREMIO	6 mm
	L/H Rear Tyre	205/60 R16	PREMIO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	15/12/2020	Inspection Date	22/12/2020
	Survey held at	60 JALAN LAM HUAT, #05-21		
	Repairer	MCGAP WORKSHOP		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	