

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|---|--|--------------------|------------------------|--|
| | SOMPO INSURAN | CE SINGAPORE PL | Ref: | CS/SMO20014265/EUqd3n2 | |
| | 50 RAFFLES PLAC SINGAPORE LAND | CE #03-03 D TOWERSINGAPORE 048623 | Date: | 05/04/2021 | |
| | | | Code: | SMO | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBJ 761K | Veh. Inspected | GBG 9675H | |
| | Policy No. | D20MTHCVE000222 | Coverage (\$) | 0.00 | |
| | Claim No. | CMTD2003734/THE | Excess (\$) | 0.00 | |
| | Assign From | GRACE TEO | Assign Date | 22/12/2020 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | NISSAN NV350 | c.c | 2488 | |
| | Engine No. | HIDDEN | Year of Reg. | 2017 | |
| | Chassis No. | JN1MC2E26Z0009664 | Colour | SILVER | |
| | Odometer | 99017 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| | General | GOOD | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195 R15C | TRAVIA | 4 mm | |
| | L/H Front Tyre | 195 R15C | TRAVIA | 4 mm | |
| | R/H Rear Tyre | 195 R15C | TRAVIA | 4 mm | |
| | L/H Rear Tyre | 195 R15C | TRAVIA | 4 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 17/12/2020 | Inspection Date | 22/03/2021 | |
| | Survey held at | EFFICIENT MOTOR & ENGINEE | RING WORKS PTE LTD | | |
| | | 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days | | | | |
| | | | | | |