

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5188T****AAD2012-127**

*Not Notified*  
*Permy B4paint*  
*82145.90*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

21 DEC 2020

**SHD5188T**

JTDKB3FU903077057

TOYOTA

PRIUS

16/12/2020

**CHINA**

22/11/2018

PART		LIST	
1	COVER, REAR BUMPER	\$	<i>BL</i> 442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>R</i> 332.70 X
1	GUARD, REAR BUMPER, CENTER	\$	<i>Not in</i> 576.30 ✓
1	COVER, REAR BUMPER, LOWER	\$	<i>SL</i> 15.40 X
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>SL</i> 116.50 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>SL</i> 117.70 X
1	FILLER, REAR BUMPER EXTENSION, RH	\$	<i>SL</i> 123.70 X
1	SEAL, REAR BUMPER SIDE, LH	\$	<i>SL</i> 88.50 X
1	SEAL, REAR BUMPER SIDE, RH	\$	<i>Dis</i> 88.50 ✓
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	<i>CRS</i> 451.80 ✓
1	LENS AND BODY, REAR LAMP, RH	\$	<i>SL</i> 502.00 ✓
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 650.30 X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	<i>SL</i> 175.10 X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	<i>SL</i> 241.90 X
1	COVER, REAR FLOOR (CTR)	\$	<i>SL</i> 229.90 X
<b>TOTAL</b>		<b>\$</b>	<b>3,506.00</b>
<b>25%</b>		<b>\$</b>	<b>876.50</b>
		<b>\$</b>	<b>2,629.50</b>

**Special Nett**

1SET PARKING AID	\$	<i>SL</i> 700.00 X
1SET REAR BUMPER CLIP	\$	<i>SL</i> 95.00 <i>60SL</i>
1 REAR BUMPER PROTECTOR	\$	<i>SL</i> 180.00 <i>30SL</i>
1SET REAR FENDER LINER CLIP	\$	<i>SL</i> 85.00 X
1SET REAR BUMPER RETAINER CLIP	\$	<i>SL</i> 85.00 X
1 REAR NUMBER PLATE WITH HOLDER	\$	<i>SL</i> 140.00 X
1SET TAILLAMP LOWER CLIP	\$	<i>SL</i> 55.00 <i>10SL</i>
1SET TAILLAMP UPPER CLIP	\$	<i>SL</i> 55.00 <i>10SL</i>

**Trans-cab Auto Services Pte Ltd**

AAD2012-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5188T**

1 END PANEL TRIM CLIP

	\$	<i>nn</i>	65.00	X
<b>TOTAL</b>	\$		<b>1,460.00</b>	

<b>TOTAL PARTS</b>	\$		<b>4,089.50</b>	
--------------------	----	--	-----------------	--

**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	<i>nn</i>	380.00	X
----	-----------	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		2,200.00	<i>2000</i>
----	--	----------	-------------

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	<i>nn</i>	380.00	X
----	-----------	--------	---

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$	<i>nn</i>	180.00	X
----	-----------	--------	---

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$	<i>nn</i>	480.00	X
----	-----------	--------	---

To transfer of Fender fittings, attachments and perform water seepage test.

\$	<i>nn</i>	480.00	X
----	-----------	--------	---

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$	<i>nn</i>	380.00	X
----	-----------	--------	---

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	<i>nn</i>	380.00	X
----	-----------	--------	---

To check steering geometry and computer wheel alignment

\$	<i>nn</i>	220.00	X
----	-----------	--------	---

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	<i>nn</i>	250.00	X
----	-----------	--------	---

Towing Fees

\$	<i>nn</i>	150.00	X
----	-----------	--------	---

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5188T****AAD2012-127**

Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	2200	
To reinstall rear bumper parking sensor.	\$	170.00	500	
To Check Electrical Lighting Concerned.	\$	170.00	200	
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	nn	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	4	X
To replace, refix and top up coolant for radiator	\$	170.00	4	X
To lift-up / out engine with gear box and refit.	\$	440.00	4	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	4	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	4	X
<b>TOTAL</b>	<b>\$</b>	<b>9,990.00</b>		
<b>Over All Total</b>	<b>\$</b>	<b>14,079.50</b>		

**(PART-BY-PART) Repair Days****25 DAYS**  
**2 days****For Official Use**Prepared By : \_\_\_\_\_  
(Accident Dept)

Verify By : \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_