

ASS. REC. BY:


REF: LPC/Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Yee Ahn
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 08 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STM 2722E Yr Regn: 12, 08.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toy Altis c.c. 1500
 Colour: M. Green A/C: Insured / Std / NI / NA
 Sp. Reading: 175.330 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: NR053 EEE106125839Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 19/12/20

Survey held at _____

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 22/12/2020

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
& 1st

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS, SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No: ES2000117
Date: 22 Dec 2020

TEL: 62507388
ATTN: Motor Claim Department

FAX: 62933767

Policy No:
Veh Reg No: SJM2772E
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: -
Claim Type: Third Party
Accident Date: 19/12/2020
TP Veh Reg No: SJN4889J

Not Authored
L/Sing &
Recovery After Repair
8 days

Chassis No: MR053ZEE106125839
Engine No: 3ZZ4819061
Reg. Date: 26/12/2008

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT NUMBER PLATE	60.00	1 PC	By 60.00	955.00
2 REAR NUMBER PLATE	60.00	1 PC	Sm 60.00	X
3 REVERSE SENSORS	300.00	1 SET	Red 300.00	200.00
			420.00	420.00
Spare Parts				
4 FRONT BUMPER	850.10	1 PC	Red 850.10	✓
5 FRONT BUMPER REINFORCEMENT	450.70	1 PC		7
6 FRONT BUMPER SIDE RETAINER - LH	61.30	1 PC	Sm 61.30	X
7 FRONT BUMPER SIDE RETAINER - RH	61.30	1 PC	DIV 61.30	✓
8 FRONT BUMPER CLIPS	60.00	1 SET	Red 60.00	✓
9 FRONT BUMPER LOWER GRILLE	245.60	1 PC	DIV 245.60	✓
10 FRONT GRILLE	365.00	1 PC	CM 365.00	✓
11 FRONT GRILLE EMBLEM	95.50	1 PC	Red 95.50	✓
12 FRONT GRILLE CLIPS	32.00	1 SET	Red 32.00	✓
13 HEAD LAMP - LH	925.80	1 PC	Sm 925.80	X
14 HEAD LAMP - RH	925.80	1 PC		7
15 FRONT SUPPORT PANEL	641.50	1 PC	Red 641.50	7
16 FRONT BONNET	865.00	1 PC	Red 865.00	X
17 FRONT BONNET LOCK	188.00	1 PC	Red 188.00	X
18 RADIATOR ASSY	1,145.50	1 PC	Sm 1,145.50	X
19 RADIATOR FAN MOTOR	522.10	1 PC	Sm 522.10	X
20 AIRCON CONDENSER	1,100.10	1 PC	Sm 1,100.10	X
21 AIRCON FAN ASSY	420.50	1 PC	Sm 420.50	X
22 REAR BUMPER	850.10	1 PC	Red 850.10	✓
23 REAR BUMPER BRACKET - LH	74.10	1 PC		7
24 REAR BUMPER BRACKET - RH	74.10	1 PC		7
25 REAR BUMPER SIDE RETAINER - LH	60.10	1 PC	Sm 60.10	X
26 REAR BUMPER SIDE RETAINER - RH	60.10	1 PC	Sm 60.10	X
27 REAR BUMPER CLIPS	64.00	1 SET	Red 64.00	✓
28 REAR END PANEL	509.60	1 PC	Red 509.60	✓
29 REAR END PANEL TOP GARNISH	219.70	1 PC		7
30 REAR END PANEL TOP GARNISH CLIPS	30.00	1 SET		7
31 TAIL LAMP LH	555.10	1 PC		7
32 TAIL LAMP RH	555.10	1 PC	Sm 555.10	X
33 TAIL LAMP PANEL - LH	160.20	1 PC	Red 160.20	X
34 TAIL LAMP PANEL - RH	160.20	1 PC	Red 160.20	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S: LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No: ES2000117
Date: 22 Dec 2020

TEL: 62507388 FAX: 62933767
ATTN: Motor Claim Department

Policy No:
Veh Reg No: SJM2772E
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: -
Claim Type: Third Party
Accident Date: 19/12/2020
TP Veh Reg No: SJN4889J

Chassis No: MR053ZEE106125839
Engine No: 3ZZ4819061
Reg. Date: 26/12/2008

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 REAR TAILGATE	950.10	1 PC	950.10	✓
36 REAR TAILGATE WEATHERSTRIP	250.20	1 PC	250.20	502in
37 REAR TAILGATE LOCK	154.20	1 PC	154.20	✓
38 REAR TAILGATE OUTER MOULDING	225.10	1 PC	225.10	X
39 REAR TAILGATE REFLECTOR - LH	450.50	1 PC	450.50	X
40 REAR TAILGATE REFLECTOR - RH	450.50	1 PC	450.50	X
41 REAR TAILGATE EMBLEM 'LOGO'	65.00	1 PC	65.00	✓
42 REAR TAILGATE INNER TRIMBOARD	336.30	1 PC	336.30	X
43 REAR FENDER INNER GARNISH - LH	385.50	1 PC	385.50	X
44 REAR FENDER INNER GARNISH - RH	385.50	1 PC	385.50	X
45 REAR BOOT LID '1.6' EMBLEM	50.50	1 PC	50.50	✓
46 REAR BOOT LID 'COROLLA ALTIS' EMBLEM	85.50	1 PC	85.50	✓
47 REAR BUMPER SPONGE	265.00	1 PC	265.00	✓
48 SPARE WHEEL PANEL	885.10	1 PC	885.10	X
49 SPARE WHEEL TOP COVER	325.30	1 PC	325.30	X
50 WATER COOLANT	60.00	1 PC	60.00	?
			17,652.50	17,652.50
Labour				
51 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	900
52 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	1000
53 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	60
54 TO REMOVE/RENEW AIRCON CONDENSER & REFILL GAS	80.00	1 JOB	80.00	?
55 TO REMOVE/TRANSFER TAILGATE MECHANISMS.	120.00	1 JOB	120.00	50
56 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	40
			4,030.00	4,030.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/12/2020 18:30 (SGT)
Date of Accident	19/12/2020 13:15 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	ALONG BKE TOWARDS SLE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM2772E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MUHAMMAD FAREEZ BIN MUSA
NRIC No	SXXXX099Z
Email Address	anesjaja04@gmail.com
Mobile Phone No	(Phone) +65-94230701
Alternative Phone No	(Home) +65-94230701

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5106769390-01
Cover Note Number	-

DRIVER

Name of Driver	SITI HAJAR BINTE MUSTAFA
NRIC No	SXXXX047E
Date Of Birth	14/01/1991
Occupation	Indoor

Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

10/02/2012
8 YEARS AND 10 MONTHS
Female
(Phone) +65-94230701
-
siti.hajar.mustafa@skh.com.sg
APT BLK 783D WOODLANDS RISE
#06-21 SINGAPORE
734783
No
Spouse
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Chain Collision
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
3
Yes
No
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Woodlands Division Headquarters
(Phone) +65-18004660000
1 Woodlands St 12 Singapore 738622
No
-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED

ATTACHMENT(S)


Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address

SJN4889J
-
-
-
-
Private car
-
-
-

→  → SLE

BKE

Refer to Police Report

Police Report No: L/20201219/7015

BACK vehicle ~~SN~~ SN4884J hit my car at the back causing my car to move. Due to the impact of the hit, my car moved and hit the front car SMK33282.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No: