

ASS. REC. BY:

REF:

LPC / 200142691K7

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP.

12/24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STM 2772E

Yr Regn:

12, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy A/T/S

c.c

1598

Colour

M. Green

A/C:

Insured / Std / NI / NA

Sp. Reading

175.330

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR0538EE108125839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

19/12/20

D.O.I.

22/12/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to Rtg @ 8227.00

311 61 Rtg @ 5500.00 - Confirmed (Red: 1660.25; 1500)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/12/2020 18:30 (SGT)
Date of Accident	19/12/2020 13:15 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	ALONG BKE TOWARDS SLE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM2772E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	MUHAMMAD FAREEZ BIN MUSA
NRIC No	SXXXX099Z
Email Address	anesjaja04@gmail.com
Mobile Phone No	(Phone) +65-94230701
Alternative Phone No	(Home) +65-94230701

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5106769390-01
Cover Note Number	-

DRIVER

Name of Driver	SITI HAJAR BINTE MUSTAFA
NRIC No	SXXXX047E
Date Of Birth	14/01/1991
Occupation	Indoor



Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMK3328Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


INJURED PERSONS DETAILS

INJURED 1

Name of injured person	SITI HAJAR BINTE MUSTAFA
Address	APT BLK 783D WOODLANDS RISE
Address Complement	#06-21 SINGAPORE
Post Code	734783
Approximate Age Years Old	29
Injuries Sustained	REFER REPORT. 5 DAYS MC.
Injured person in which vehicle?	SJM2772E
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

(A) SJM2772E (B) SJN4889J (C) SMK3328Z



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Police Report No. L/20201219/7015

On 19/12/2020, @ 1315hr, driving from BKE to SLE. Front car SMK3328Z slowed down, my vehicle SJM2772E managed to break and at stationary.

Back vehicle ~~SJM~~ SJN4889J hit my car at the back causing my car to move. Due to the impact of the hit, my car moved and hit the front car SMK3328Z.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte Ltd@gmail.com

Registration No: 201719251W GST No: 201719251W

(1)

M/S : LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No: ES2000117
Date: 22 Dec 2020

TEL: 62507388
ATTN: Motor Claim Department

FAX: 62933767

Policy No:
Veh Reg No: SJM2772E
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: -
Claim Type: Third Party
Accident Date: 19/12/2020
TP Veh Reg No: SJN4889J

Not Authored

L/Sing @ 550dp

Running After Repair

Chassis No: MR053ZEE106125839
Engine No: 3ZZ4819061
Reg. Date: 26/12/2008

8 days

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT NUMBER PLATE	60.00	1 PC	60.00	455.00
2 REAR NUMBER PLATE	60.00	1 PC	60.00	X
3 REVERSE SENSORS	300.00	1 SET	300.00	200.00
			420.00	420.00
Spare Parts				
4 FRONT BUMPER	850.10	1 PC	850.10	✓
5 FRONT BUMPER REINFORCEMENT	450.70	1 PC	450.70	2
6 FRONT BUMPER SIDE RETAINER - LH	61.30	1 PC	61.30	X
7 FRONT BUMPER SIDE RETAINER - RH	61.30	1 PC	61.30	✓
8 FRONT BUMPER CLIPS	60.00	1 SET	60.00	✓
9 FRONT BUMPER LOWER GRILLE	245.60	1 PC	245.60	✓
10 FRONT GRILLE	365.00	1 PC	365.00	✓
11 FRONT GRILLE EMBLEM	95.50	1 PC	95.50	✓
12 FRONT GRILLE CLIPS	32.00	1 SET	32.00	✓
13 HEAD LAMP - LH	925.80	1 PC	925.80	X
14 HEAD LAMP - RH	925.80	1 PC	925.80	2
15 FRONT SUPPORT PANEL	641.50	1 PC	641.50	2
16 FRONT BONNET	865.00	1 PC	865.00	X
17 FRONT BONNET LOCK	188.00	1 PC	188.00	X
18 RADIATOR ASSY	1,145.50	1 PC	1,145.50	X
19 RADIATOR FAN MOTOR	522.10	1 PC	522.10	X
20 AIRCON CONDENSER	1,100.10	1 PC	1,100.10	X
21 AIRCON FAN ASSY	420.50	1 PC	420.50	X
22 REAR BUMPER	850.10	1 PC	850.10	✓
23 REAR BUMPER BRACKET - LH	74.10	1 PC	74.10	X
24 REAR BUMPER BRACKET - RH	74.10	1 PC	74.10	X
25 REAR BUMPER SIDE RETAINER - LH	60.10	1 PC	60.10	X
26 REAR BUMPER SIDE RETAINER - RH	60.10	1 PC	60.10	X
27 REAR BUMPER CLIPS	64.00	1 SET	64.00	✓
28 REAR END PANEL	509.60	1 PC	509.60	✓
29 REAR END PANEL TOP GARNISH	219.70	1 PC	219.70	2
30 REAR END PANEL TOP GARNISH CLIPS	30.00	1 SET	30.00	2
31 TAIL LAMP LH	555.10	1 PC	555.10	2
32 TAIL LAMP RH	555.10	1 PC	555.10	X
33 TAIL LAMP PANEL - LH	160.20	1 PC	160.20	X
34 TAIL LAMP PANEL - RH	160.20	1 PC	160.20	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/07. THE CONCOURSE

Estimate No: ES2000117

Date: 22 Dec 2020

Policy No:

Veh Reg No: SJM2772E

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053ZEE106125839

Engine No: 3ZZ4819061

Reg. Date: 26/12/2008

TEL: 62507388

FAX: 62933767

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 19/12/2020

TP Veh Reg No: SJN4889J

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
35 REAR TAILGATE	680.40	1 PC	950.10	SS
36 REAR TAILGATE WEATHERSTRIP	197.80	1 PC	250.20	502.10 98.80 SN
37 REAR TAILGATE LOCK		1 PC	154.20	
38 REAR TAILGATE OUTER MOULDING		1 PC	225.10	X
39 REAR TAILGATE REFLECTOR - LH		1 PC	450.50	X
40 REAR TAILGATE REFLECTOR - RH		1 PC	450.50	X
41 REAR TAILGATE EMBLEM 'LOGO'		1 PC	65.00	
42 REAR TAILGATE INNER TRIMBOARD		1 PC	336.30	X
43 REAR FENDER INNER GARNISH - LH		1 PC	385.50	X
44 REAR FENDER INNER GARNISH - RH		1 PC	385.50	X
45 REAR BOOT LID '1.6' EMBLEM		1 PC	50.50	
46 REAR BOOT LID 'COROLLA ALTIS' EMBLEM		1 PC	85.50	
47 REAR BUMPER SPONGE	198.80	1 PC	265.00	
48 SPARE WHEEL PANEL		1 PC	885.10	X
49 SPARE WHEEL TOP COVER		1 PC	325.30	X
50 WATER COOLANT	259	1 PC	60.00	2012
			17,652.50	17,652.50
Labour				
51 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	900
52 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	1000
53 TO APPLY RUST- PROOFING ON REPAIRED. REPLACED PANEL.	150.00	1 JOB	150.00	60
54 TO REMOVE/RENEW AIRCON CONDENSER & REFILL GAS	80.00	1 JOB	80.00	2
55 TO REMOVE/TRANSFER TAILGATE MECHANISMS.	120.00	1 JOB	120.00	50
56 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	40
			4,030.00	4,030.00



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S : LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/07, THE CONCOURSE

TEL: 62507388 FAX: 62933767
ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 19/12/2020
TP Veh Reg No: SJN4889J

Estimate No: ES2000117
Date: 22 Dec 2020
Policy No:
Veh Reg No: SJM2772E
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053ZEE106125839
Engine No: 3ZZ4819061
Reg. Date: 26/12/2008

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 22,102.50
			Add GST @ 7%	1,547.18
			Total Amount Payable	S\$ 23,649.68

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND SIX HUNDRED FORTY NINE AND CENTS SIXTY EIGHT ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S: LONPAC INSURANCE BHD

300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No: ES2000117

Date: 22 Dec 2020

Policy No:

TEL: 62507388

FAX: 62933767

Veh Reg No: SJM2772E

ATTN: Motor Claim Department

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: -

Claim Type: Third Party

Chassis No: MR053ZEE106125839

Accident Date: 19/12/2020

Engine No: 3ZZ4819061

TP Veh Reg No: SJN4889J

Reg. Date: 26/12/2008

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT NUMBER PLATE	60.00	1 PC	60.00	85.00
2 REAR NUMBER PLATE	60.00	1 PC	60.00	X
3 REVERSE SENSORS	300.00	1 SET	300.00	200.00
			420.00	420.00
Spare Parts				
4 FRONT BUMPER	850.10	1 PC	850.10	✓
5 FRONT BUMPER REINFORCEMENT	450.70	1 PC	450.70	✓
6 FRONT BUMPER SIDE RETAINER - LH	61.30	1 PC	61.30	X
7 FRONT BUMPER SIDE RETAINER - RH	61.30	1 PC	61.30	✓
8 FRONT BUMPER CLIPS	60.00	1 SET	60.00	✓
9 FRONT BUMPER LOWER GRILLE	245.60	1 PC	245.60	✓
10 FRONT GRILLE	365.00	1 PC	365.00	✓
11 FRONT GRILLE EMBLEM	95.50	1 PC	95.50	✓
12 FRONT GRILLE CLIPS	32.00	1 SET	32.00	✓
13 HEAD LAMP - LH	925.80	1 PC	925.80	X
14 HEAD LAMP - RH	925.80	1 PC	925.80	✓
15 FRONT SUPPORT PANEL	641.50	1 PC	641.50	✓
16 FRONT BONNET	865.00	1 PC	865.00	X
17 FRONT BONNET LOCK	188.00	1 PC	188.00	X
18 RADIATOR ASSY	1,145.50	1 PC	1,145.50	X
19 RADIATOR FAN MOTOR	522.10	1 PC	522.10	X
20 AIRCON CONDENSER	1,100.10	1 PC	1,100.10	X
21 AIRCON FAN ASSY	420.50	1 PC	420.50	X
22 REAR BUMPER	850.10	1 PC	850.10	✓
23 REAR BUMPER BRACKET - LH	74.10	1 PC	74.10	X
24 REAR BUMPER BRACKET - RH	74.10	1 PC	74.10	X
25 REAR BUMPER SIDE RETAINER - LH	60.10	1 PC	60.10	X
26 REAR BUMPER SIDE RETAINER - RH	60.10	1 PC	60.10	X
27 REAR BUMPER CLIPS	64.00	1 SET	64.00	✓
28 REAR END PANEL	509.60	1 PC	509.60	✓
29 REAR END PANEL TOP GARNISH	219.70	1 PC	219.70	✓
30 REAR END PANEL TOP GARNISH CLIPS	30.00	1 SET	30.00	✓
31 TAIL LAMP LH	555.10	1 PC	555.10	✓
32 TAIL LAMP RH	555.10	1 PC	555.10	X
33 TAILLAMP PANEL - LH	160.20	1 PC	160.20	X
34 TAILLAMP PANEL - RH	160.20	1 PC	160.20	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S: LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No: ES2000117

Date: 22 Dec 2020

Policy No:

TEL: 62507388

FAX: 62933767

Veh Reg No: SJM2772E

ATTN: Motor Claim Department

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: -

Chassis No: MR053ZEE106125839

Claim Type: Third Party

Engine No: 3ZZ4819061

Accident Date: 19/12/2020

Reg. Date: 26/12/2008

TP Veh Reg No: SJN4889J

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 REAR TAILGATE	950.10	1 PC	950.10	✓
36 REAR TAILGATE WEATHERSTRIP	250.20	1 PC	250.20	502.10
37 REAR TAILGATE LOCK	154.20	1 PC	154.20	✓
38 REAR TAILGATE OUTER MOULDING	225.10	1 PC	225.10	X
39 REAR TAILGATE REFLECTOR - LH	450.50	1 PC	450.50	X
40 REAR TAILGATE REFLECTOR - RH	450.50	1 PC	450.50	X
41 REAR TAILGATE EMBLEM 'LOGO'	65.00	1 PC	65.00	✓
42 REAR TAILGATE INNER TRIMBOARD	336.30	1 PC	336.30	X
43 REAR FENDER INNER GARNISH - LH	385.50	1 PC	385.50	X
44 REAR FENDER INNER GARNISH - RH	385.50	1 PC	385.50	X
45 REAR BOOT LID '1.6' EMBLEM	50.50	1 PC	50.50	✓
46 REAR BOOT LID 'COROLLA ALTIS' EMBLEM	85.50	1 PC	85.50	✓
47 REAR BUMPER SPONGE	265.00	1 PC	265.00	✓
48 SPARE WHEEL PANEL	885.10	1 PC	885.10	X
49 SPARE WHEEL TOP COVER	325.30	1 PC	325.30	X
50 WATER COOLANT	60.00	1 PC	60.00	205.00
			17,652.50	17,652.50

Labour

51 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	900.00
52 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	1000.00
53 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	60.00
54 TO REMOVE/RENEW AIRCON CONDENSER & REFILL GAS	80.00	1 JOB	80.00	2.00
55 TO REMOVE/TRANSFER TAILGATE MECHANISMS.	120.00	1 JOB	120.00	50.00
56 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	40.00
			4,030.00	4,030.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S : LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/07, THE CONCOURSE

TEL: 62507388 FAX: 62933767
ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 19/12/2020
TP Veh Reg No: SJN4889J

Estimate No: ES2000117
Date: 22 Dec 2020
Policy No:
Veh Reg No: SJM2772E
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053ZEE106125839
Engine No: 3ZZ4819061
Reg. Date: 26/12/2008

Estimate Repair Cost to Vehicle No :SJM2772E

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 22,102.50
			Add GST @ 7%	1,547.18
			Total Amount Payable	SS 23,649.68

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND SIX HUNDRED FORTY NINE AND CENTS SIXTY EIGHT ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE