

## **SMRT Accident Vehicle Repair Estimates**

Section A - Accident Details				
Registration Number	SMB1350T			
Case Reference Number	BUS/12/20/7019			
Registration Date	15/4/2013			
Company Type	SMRT Buses Ltd			
Make	MAN			
Model	MAN NL320F(A22)			
Name of Driver	Goh Eng Chuang			
Type of Accident	Side Swipe			
Accident Date and Time	16/12/2020 12:10 PM			
Accident Reported Date and Time	16/12/2020 2:15 PM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number	24109227			
Special Instruction to ARC,if any	SMB1324T - RIGHT VIEW MIRROR YL3541B (TP) - INSURED WITH CHINA TAIPING			
Prepared Date and Time	19/12/2020 8:58 AM			
Chassis Number	WMAA22ZZ1D7001797			
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Rep	pair Estimates				
Summary of Repair Estimates						
	Quotation from ARC	Adjusted by Surveyor, if applicable				
Total Labour Cost	\$265.00	\$132.50				
Total Spray Cost	\$0.00	\$0.00				
Total Spare Part Cost	\$896.33	\$896.33				
Total Other Cost	\$0.00	\$0.00				
TOTAL COST	\$1,161.33	\$1,028.83				
Lump Sum Total	\$0.00	\$1,050.00				
Number of Repair Days	1.0	0.5				
Prepared / Adjusted By	Kok Khoon Goh	Sun Pin (LKK)				
ARC / Surveyor Sign Off Date	19/12/2020 8:59 AM	26/12/2020 10:42 AM				
Signature	2	5				
Remarks						

Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

## SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 04/03/2021
User ID : CatherineLee



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 04/03/2021

**User ID** : CatherineLee

			Section	on D - Deta	ils of Repair E	stimates			
Part 1 - Labo	ur Works								
lob Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$265.00				\$132.50		
			\$265.00				\$132.50		
Part 2 - Spray	/ Painting & P	anel Beating Rela	ted Works						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Spray Painting & Panel Beating									
Part 3 - Other	Costs - Accid	dent and Accident	Repair Related Expens	se					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare	Parts / Mater	ial Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01- ACCE467	MIRROR,VIEW:FRONT,R H,FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace / CRA
Total					\$1,244.90		\$1,120.41		
Added Spare	Parts / Materi	al Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,120.41 - 20% 896.33 132.50 LIS \$1,050 0.5 days half days 1,028.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer