



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ESTIMATE

NO : QUOT202012-000016(00)

DATE : 22/12/2020

POLICY NO : 999995580

VEH REG NO : SKZ5855A

MAKE/MODEL : B.M.W. 320i LED HL

CHASSIS NO : WBA5F320X0FJ50386

ENGINE NO : F8563622B48B20A

REG. DATE : 2020

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE


ACCIDENT DATE : 03/12/2020

Not Authorized
Resurvey B4 paint

Today
22/12/2020

Estimate Repair Cost to Vehicle No : SKZ5855A

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
PARTS			
1 Rear door - RH	1	1,680.00 <i>B1</i>	1,680.00 ✓
2 Rear door weatherstrip - RH	1	225.00 <i>me</i>	225.00 ✓
3 Rear door trimboard rivets - RH <i>necessary</i>	20	10.50 <i>60SN</i>	210.00 ?✓
4 Rear door outer handle - RH	1	188.00 <i>Bu</i>	188.00 ✓
5 Rear door outer handle grip - RH	1	25.00 <i>mi</i>	25.00 ✓
6 Rear fender - RH	1 <i>B1</i>	2,100.00	2,100.00 ✓
7 Rear fender inner panel - RH	1	1,625.00 <i>R</i>	1,625.00 X
8 Rear fender inner shield - RH	1	230.00	230.00 ✓✓
9 Rear fender inner shield clips - RH	20	6.50 <i>50SN</i>	130.00 ✓
10 Rear petrol flap	1	85.00 <i>mi</i>	85.00 ✓
11 Rear Petrol housing	1	158.00 <i>CMT</i>	158.00 ✓
12 Rear bumper	1 <i>AT/CMT</i>	1,550.00	1,550.00 ✓
13 Rear bumper side retainer - RH	1	265.00 <i>CMT</i>	265.00 ✓
14 Rear bumper sensor	1	255.00 <i>fu</i>	255.00 X
15 Rear bumper sensor seals	6	12.00 <i>me</i>	72.00 ✓
16 Rear bumper clips	15 <i>50SN</i>	5.50 <i>me</i>	82.50 ✓
17 Taillamp assy - RH	1	695.00	695.00 ?
<i>Rear fender inner fuse box cover \$ 78.00</i>			9,575.50
			Add 10%
			957.55
			10,533.05
SPECIAL NET			
18 Rear windscreen sealant	1	60.00 <i>me</i>	60.00 <i>40SN</i>
			60.00 <i>200</i>
LABOUR			
19 To remove and refit rear windscreen glass	1	150.00	150.00 <i>1201</i>
20 To remove and refit rear petrol tank	1	220.00	220.00 <i>601</i>
21 To remove and refit RH rear interior garnishes, trimboards and speaker board to facilitates the repairs	1	280.00	280.00 <i>1201</i>
22 To transfer RH rear damaged door interior mechanism and glass to new door	1	150.00	150.00 <i>601</i>
23 To panel beat and straighten RH rear chassis frame, RH rear door pillar,, to cut and weld RH rear fender, RH rear fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,500.00	1,500.00 <i>9001</i>
24 To putty and spray paint on affected areas	1	1,200.00	1,200.00 <i>6601</i>
			3,500.00 <i>1920</i>



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 03/12/2020

ESTIMATE

NO : QUOT202012-000016(00)

DATE : 22/12/2020

POLICY NO : 999995580

VEH REG NO : SKZ5855A

MAKE/MODEL : B.M.W. 320I LED HL

CHASSIS NO : WBA5F320X0FJ50386

ENGINE NO : F8563622B48B20A

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SKZ5855A

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 14,093.05
		ADD GST @ 7%	986.51
		GRAND TOTAL	S\$ 15,079.56

SINGAPORE DOLLAR FIFTEEN THOUSAND SEVENTY-NINE AND CENTS FIFTY-SIX ONLY

~~S\$~~ 9,441.60
XS 1,200.00

~~S\$~~ 8,241.60
7% 576.91

~~S\$~~ 8,818.51

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE