



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 03/12/2020

FAX : 6415 3723

ESTIMATE

NO : QUOT202012-000016(00)

DATE : 22/12/2020

POLICY NO : 999995580

VEH REG NO : SKZ5855A

MAKE/MODEL : B.M.W. 320i LED HL

CHASSIS NO : WBA5F320X0FJ50386

ENGINE NO : F8563622B48B20A

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SKZ5855A

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear door - RH ✓	1	1,680.00	1,680.00 ✓
2 Rear door weatherstrip - RH ✓	1	225.00	225.00 ✓
3 Rear door trimboard rivets - RH	20	10.50	210.00 601
4 Rear door outer handle - RH ✓	1	188.00	188.00 ✓
5 Rear door outer handle grip - RH ✓	1	25.00	25.00 ✓
6 Rear fender - RH ✓	1	2,100.00	2,100.00 ✓
7 Rear fender inner panel- RH	1	1,625.00	1,625.00 X
8 Rear fender inner shield - RH ✓	1	230.00	230.00 ✓
9 Rear fender inner shield clips - RH	20	6.50	130.00 501
10 Rear petrol flap ✓	1	85.00	85.00 ✓
11 Rear Petrol housing ✓	1	158.00	158.00 ✓
12 Rear bumper ✓	1	1,550.00	1,550.00 ✓
13 Rear bumper side retainer - RH ✓	1	265.00	265.00 ✓
14 Rear bumper sensor	1	255.00	255.00 X
15 Rear bumper sensor seals ✓	6	12.00	72.00 ✓
16 Rear bumper clips	15	5.50	82.50 501
17 Taillamp assy - RH	1	695.00	695.00 X
			9,575.50
			Add 10% 957.55
			10,533.05
SPECIAL NET			
18 Rear windscreen sealant	1	60.00	60.00 401
			60.00
LABOUR			
19 To remove and refit rear windscreen glass	1	150.00	150.00 1201
20 To remove and refit rear petrol tank	1	220.00	220.00 601
21 To remove and refit RH rear interior garnishes, trimboards and speaker board to facilitates the repairs	1	280.00	280.00 1201
22 To transfer RH rear damaged door interior mechanism and glass to new door	1	150.00	150.00 601
23 To panel beat and straighten RH rear chassis frame, RH rear door pillar, to cut and weld RH rear fender, RH rear fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,500.00	1,500.00 901
24 To putty and spray paint on affected areas	1	1,200.00	1,200.00 6601
			3,500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rear fender inner fender box cover @ 78.00 each

Not Authorized
Resurvey B4 paint
@ 9441.60
7 days
22/12/2020