

ASS. REC. BY:

REF: A161Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8172k

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 07 days

Res.: Yes or No

Lum Sum: 1.8.1 %

3 Val.: Yes or No

CA / REV REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SK 85855AYr Regn: 09, 20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: BMWc.g. 1998Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 7914

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA 5F320 \* OF J50386Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD / R/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 1 tankok

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 3/12/20D.O.I. 22/12/2020

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S - RS. \$

F. m/s

Others

TOTAL

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 03/12/2020

## ESTIMATE

NO : QUOT202012-000016(00)

DATE : 22/12/2020

POLICY NO : 999995580

VEH REG NO : SKZ5855A

MAKE/MODEL : B.M.W. 320I LED HL

CHASSIS NO : WBA5F320X0FJ50386

ENGINE NO : F8563622B48B20A

REG. DATE : 2020

## Estimate Repair Cost to Vehicle No : SKZ5855A

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>PARTS</b>			
1 Rear door - RH	1	1,680.00	1,680.00
2 Rear door weatherstrip - RH	1	225.00	225.00
3 Rear door trimboard rivets - RH	20	10.50	210.00
4 Rear door outer handle - RH	1	188.00	188.00
5 Rear door outer handle grip - RH	1	25.00	25.00
6 Rear fender - RH	1	2,100.00	2,100.00
7 Rear fender inner panel- RH	1	1,625.00	1,625.00
8 Rear fender inner shield - RH	1	230.00	230.00
9 Rear fender inner shield clips - RH	20	6.50	130.00
10 Rear petrol flap	1	85.00	85.00
11 Rear Petrol housing	1	158.00	158.00
12 Rear bumper	1	1,550.00	1,550.00
13 Rear bumper side retainer - RH	1	265.00	265.00
14 Rear bumper sensor	1	255.00	255.00
15 Rear bumper sensor seals	6	12.00	72.00
16 Rear bumper clips	15	5.50	82.50
17 Taillamp assy - RH	1	695.00	695.00
			9,575.50
		Add 10%	957.55
			10,533.05
<b>SPECIAL NET</b>			
18 Rear windscreen sealant	1	60.00	60.00
			60.00
<b>LABOUR</b>			
19 To remove and refit rear windscreen glass	1	150.00	150.00
20 To remove and refit rear petrol tank	1	220.00	220.00
21 To remove and refit RH rear interior garnishes, trimboards and speaker board to facilitates the repairs	1	280.00	280.00
22 To transfer RH rear damaged door interior mechanism and glass to new door	1	150.00	150.00
23 To panel beat and straighten RH rear chassis frame, RH rear door pillar, to cut and weld RH rear fender, RH rear fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,500.00	1,500.00
24 To putty and spray paint on affected areas	1	1,200.00	1,200.00
			3,500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	05/12/2020 09:52 (SGT)
Date of Accident	03/12/2020 09:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG CTE TOWARDS CITY AFTER YIO CHU KANG ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ5855A
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Company Reg No	1XXXXX778Z
Email Address	derrick.lee@daimler.com
Mobile Phone No	(Phone) +65-82821711
Alternative Phone No	(Office) +65-68498118

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	320i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	-

### DRIVER

Name of Driver	DARRYL TAN SUSHEELAN
NRIC No	SXXXX352A
Date Of Birth	16/11/1982
Occupation	Indoor

Date Of Driving Pass	03/10/2005
Driving experience	15 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94511966
Alt. Phone Number	-
Email Address	darrylts@gmail.com
Address	NA
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD, AS I WAS DRIVING INTO THE MAIN ROAD, FROM A SLIP ROAD, AND WHEN MY VEHICLE WAS ALREADY ON THE MAIN ROAD, IT WAS HIT BY VEHICLE B FROM THE REAR. I WISHED TO STATE THAT I WAS ALREADY ON THE MAIN ROAD, AS SHOWN IN MY IN CAR VIDEO, WHEN VEHICLE B HIT MY VEHICLE FROM THE REAR. NO ONE WAS CONVEY TO HOSPITAL BUT I WILL BE SEEING A DOCTOR FOR MY UPPER BACK PAIN.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1492X
Vehicle Manufacturer	Iveco
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Commercial vehicle TOH KAH PIEW

 Accident report SA0A20C50001



# REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S 8 2 3 6 3 5 2 A**

Name:

**DARRYL TAN SUSHEEDAN**

Birth Date: **16 Nov 1982**

Issue Date: **05 Oct 2005**





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

03 Oct 2005

**Class 3** Motor cars  $\leq$  3000 kg with  $\leq$  7 passengers,  
exclusive of the driver; and motor tractors  
/vehicles  $\leq$  2500 kg

NP 428A

Licence No: S8236352A

