

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST301/30/TP

Your Ref: TP claim against SBC4444L

21-Dec-20

China TaiPing Insurance (S) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Xiao Chen

Attn: Motor Claims Department

Dear Sir/Ms,

MR053REH104562510

Re: Estimated cost of repair to Toyota Altis no: SLK1857M

Date of accident: 18-12-2020

Parts supply:

- 1 pc Bootlid *Buckled*
- 1 pc Bootlid emblem - Logo *2 pc*
- 1 pc Bootlid emblem - COROLLA *2 pc*
- 1 pc Bootlid emblem - ALTIS
- 2 pcs Bootlid lamp @\$371.75 *LH cut*
- 2 pcs Bootlid hinges @\$182.05 *new*
- 1 pc Bootlid weatherstrip *cut*
- 1 pc Bootlid inner lock *new*
- 1 pc Bootlid insulator *new*
- 11 pcs Bootlid insulator clips @\$3.50 *new*
- 4 pcs Bootlid stoppers @12.50 *new*
- 1 pc Taillamp L/h *could*
- 1 pc Taillamp clip L/h *new*
- 1 pc Taillamp lower bracket *could* *RH Dmg*
- 1 pc Rear bumper *Disltd*
- 2 pcs Rear bumper retainers @\$90.87 *LH Dmg*
- 2 pcs Rear bumper brackets @\$181.10 *RH Dmg*
- 8 pcs Rear bumper clips @\$3.50 *new*
- 1 pc Rear bumper reinforcement *LH Dmg* *Beut*
- 2 pcs Rear bumper sensors @\$185.30 *Dmg*
- 1 pc Rear windscreen moulding *new*
- 1 pc Rear L/h fender *Disltd*
- 1 pc Rear L/h fender inner trim board *could*
- 6 pcs Rear L/h fender inner trim board clips @\$3.50 *new*
- 1 pc Rear L/h fender mudflap *new*
- 1 pc Rear L/h fender air duct *could*
- 1 pc Rear L/h fender inner panel *new*
- 1 pc Fuel tank *new*
- 1 pc Fuel tank neck *new*
- 1 pc Rear end panel *Disltd*
- 1 pc Rear end panel garnish *Disltd*
- 1 pc Rear end panel garnish inner cover *new*
- 1 pc Spare tyre panel *new*

S\$	781.40	✓
	61.10	✓
	63.90	✓
	51.90	✓
	743.50	<i>377.5 328</i>
	364.10	✓
	231.35	✓
	371.75	✓
	261.60	+
	38.50	+
	50.00	✓
	412.50	<i>391</i>
	10.00	✓
	171.25	<i>48.</i>
	571.45	✓
	181.74	✓
	362.20	<i>165</i>
	28.00	✓
	371.75	✓
	370.60	<i>200/500</i>
	133.52	✓
	1712.55	<i>586.</i>
	381.60	<i>338</i>
	21.00	✓
	98.50	+
	78.50	✓
	678.90	+
	971.75	+
	189.50	+
	381.90	✓
	371.44	<i>240</i>
	171.10	+
	10,688.85	

5443.51

4082.63

S.N: 200

807 X

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Toyota Altis no: SLK1857M

Date of accident: 18-12-2020

Parts supply:

Balance b/f:

S\$ 10,688.85
Less 25%: (2,672.21)
8,016.64

S/Nett Items

1 pc Rear windscreen gum *new*

50.00 ✓

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.

To respray affected part.

To remove & refit rear windscreen

To remove & refit rear inner trims, seat assy and roof lining to facilitate repair.

To remove & refit fuel tank.

To remove & refit rear reverse sensor.

Towing charges

To apply underseal

To remove & refit of wirings.

1200
~~1,500.00~~
~~1,600.00~~ *1200*
120.00 ✓
150.00 *80*
100.00 *80*
60.00 *50*
60.00 ✓
80.00 ✓
30.00 ✓

2900

S\$ 11,766.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/s 22/12/20.

09 Days.

total: 7232.63.

2/s: 5750.