



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20014286/Gqf3n2 Date: 11/06/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 5226X	Veh. Inspected	SMW 5566B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008449/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	22/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	BMW 523i 2.5	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAFP32090C547171	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/35 ZR19	FIRENZA	6 mm	
L/H Front Tyre	235/35 ZR19	FIRENZA	6 mm	
R/H Rear Tyre	235/35 ZR19	FIRENZA	6 mm	
L/H Rear Tyre	235/35 ZR19	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2020	Inspection Date	23/12/2020	
Survey held at	8 KAKI BUKIT AVE 4 #01-50, PREMIER @ KAKI BUKIT			
Repairer	FC GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	