

FC Garage

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875

Tel: 65 90110243

CO. Reg. No.: 53409207A

Model : **BMW 523i**Registraion No : **SMW 5566 B**Chassis No: **WBAFP32090C547171**Year of Manufacturing: **2011**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper ?	\$ 1,356.90	\$ 1,356.90
2	1	FrontBumper Retainer (LHS) X } NN	\$ 18.90	\$ 18.90
3	1	Front Bumper Bracket (LHS) X	\$ 25.70	\$ 25.70
4	1	Front Fender (LHS) / NN	\$ 926.35	\$ 926.35
5	1	Front Fender Shield (LHS) X NN	\$ 267.80	\$ 267.80
6	1	Headlight (LHS) ?	\$ 2,604.35	\$ 2,604.35
7	1	Side Mirror (LHS) repair X	\$ 678.40	\$ 678.40
8	1	Front Knuckle Hub (LHS) X	\$ 670.80	\$ 670.80
9	1	Front Wheel Bearing (LHS) X	\$ 552.45	\$ 552.45
10	1	Front Upper Arm (LHS) X } NN	\$ 555.85	\$ 555.85
11	1	Front Lower Arm (LHS) X	\$ 640.90	\$ 640.90
12	1	Front Control Arm (LHS) X	\$ 498.50	\$ 498.50
13	1	Front Shock Absorber (LHS) X	\$ 647.05	\$ 647.05
				<u>\$ 9,443.95</u>
				-5% \$ 472.20
Total for spare parts				<u>\$ 8,971.75</u>

Special Nett

1	10	Front Bumper Clip ?	\$ 9.00	\$ 90.00
2	10	LHS Front Fender Shield Clip X NN	\$ 9.00	\$ 90.00
3	1	LHS Front Sport Rim - Cat.	\$ 1,800.00	\$ 1,800.00
4	1	LHS Front Tyre X	\$ 900.00	\$ 900.00
5	1	LHS Front Fender Sealant X } NN	\$ 50.00	\$ 50.00
Total for SP				<u>\$ 2,930.00</u>
Sub-Total for Parts :				<u>\$ 11,901.75</u>

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.	\$	900.00 400
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	700.00 400
3		To check wiring system to facilitate repair and refit the same	\$	60.00 30
4		Apply rust proofing on the adjacent panels	\$	80.00 X
5		Remove and replace rear end panel lining and garnish to fac	\$	100.00 X
6		To supply under coating / putty on parts replaced	\$	50.00 X
7		Reset engine management system with diagnostic fault	\$	120.00 X
8		To perform water seepage test after repair	\$	120.00 X
9		Remove and replace bumper sensor	\$	60.00 40.
10		Remove & refit undercarriage to assist work load	\$	280.00 X NV
11		To re-adjust wheel alignment	\$	120.00 60
TOTAL AMOUNT :			\$	2,590.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 Days.

Lumpsum Repair

After repair photos

Good Q. & A.

23/12/2020.