

ans-cab Auto Services Pte Ltd

2 Ang Mo Kio Street 63 Singapore 569111

No. : 6287 6666 Fax No. : 6257 1330

/GST Reg. No. 201019626G

IC5485R

AAD2012-153

Not Authorized
Return B4 paint

3011.13

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

28 DEC 2020

SHC5485R

JTDKB3FU003077318

TOYOTA

PRIUS

19/12/2020

Sampo

06/11/2020

PART

- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 JAR ASSY, WINDSHIELD WASHER

LIST

\$	<i>By</i>	977.80	✓
\$	<i>in</i>	206.70	X
\$	<i>n</i>	1,300.70	X
\$	<i>in</i>	219.10	X

TOTAL \$ 2,704.30

25% \$ 676.08

\$ 2,028.23

Special Nett

- ET FRONT FENDER EMBLEM RH
- ET FRT FENDER CLIP
- L FRT FENDER LINER CLIP
- ET REAR BUMPER RETAINER CLIP
- TYRE
- RIM
- HUB CAP

\$	<i>in</i>	54.60	✓
\$	<i>nn</i>	95.00	X
\$	<i>nn</i>	180.00	X
\$	<i>nn</i>	85.00	<i>60.00</i>
\$	<i>in</i>	350.00	X
\$	<i>net</i>	1,879.40	✓
\$	<i>net</i>	300.00	✓

TOTAL \$ 2,944.00

TOTAL PARTS \$ 4,972.23

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion,
Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *300.*

3011.13
858.0
3031.2

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

O./GST Reg. No. 201019626G

AAD2012-153

HC5485R

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	~ 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Towing Fees	\$	4 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	4401
To Check Electrical Lighting Concerned.	\$	170.00	151
To transfer of tire, rim and on wheel balancing.	\$	220.00	201
To lift-up / out engine with gear box and refit.	\$	4 440.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	4 380.00	X

TOTAL \$ 7,950.00**Over All Total \$ 12,922.23****(PART-BY-PART) Repair Days****25 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: