

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20014290/T1VF3E2
Date: 15/01/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MS005945
Claimant Vehicle No : SHC1160D Insured Vehicle No : SML7890J
Date of Loss: 20/12/2020 Nature of Claim: TP Claim No: M2006286

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC1160D
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS080897
Reg. Date: 06/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FU503568953
Colour: Blue Odometer: 439814 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Excellent Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,388.41	439.80	1,948.61	81.59
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,150.00	750.00	400.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,549.41	1,200.80	2,348.61	66.17
Approved Total (Overridden) (S\$)		950.00		
(S\$)	3,549.41	950.00	2,599.41	73.23
+ GST 7.00/7.00% (S\$)	248.46	66.50	181.96	73.24
Nett Amount (S\$)	3,797.87	1,016.50	2,781.37	73.23

INSPECTION

Date of Assignment: 22/12/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 22/12/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2021)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1160D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER COVER	Deformed	499.90 FL	-	*499.90 FL
2	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	82.30 FL	-	*- FL
3	1		*FRONT FENDER LH	Repair	945.30 FL	-	*- FL
4	1		*FRONT FENDER EMBLEM HYBRID	Necessary	86.50 FL	-	*86.50 FL
5	1		*FRONT LH WHEEL RIM	Not Necessary	1,570.55 FL	-	*- FL
					Sub Total (S\$)	3,184.55	586.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	796.14	146.60
					Total Parts (S\$)	2,388.41	439.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	320.00
2	SPRAY PAINTING	New	500.00	400.00
3	CHECK LIGHTING	New	60.00	30.00
4	REST WHEEL ALIGNMENT	New	90.00	0.00
Gross Labour Cost (S\$)			1,150.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >