

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM20D204922/C01/TOHHS Date: 11<sup>th</sup> March 2021

Our Ref : CS/CTI20014294/Qqf3e2

## M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLT 2206M ACCIDENT ON 16/12/2020

Instruction was received to inspect the vehicle Reg. No. SLT 2206M. The inspection was conducted on 23/12/2020 at the premises of M/s Auto Insure Pte Ltd, 6 Marsiling Lane, Singapore 739145.

The following vehicle information was recorded:

Registration Number : SLT 2206M

Make/Model : Mazda CX-5 5-Door Wagon 2.0L SP.6EAT

Year of Registration : 2013 Body Colour : White

Chassis Number : JM6KE1071E0209231

Engine Capacity : 1998 cc Speedometer Reading : 129783 km

The vehicle sustained damages at the front portion, o/s and n/s body. The Estimated repair cost of such vehicle is S\$10,189.46 (Sin Dollars: Ten Thousand One Hundred Eighty-Nine and Forty-Six cents only.) (Exclude check items S\$885.00Nett) (Details see photographs enclosed)



## 51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be uneconomical to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 40,000.00

32.734.00)

Less: LTA Reimbursement Value (RV)

S\$ 7,266.00

(S\$

Less: Excess 750.00) (S\$

Nett Liability 6,516.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 10,189.46

(Exclude check items S\$885.00Nett)

Less:Excess (S\$ 750.00)

Nett Liability

9,439.46

(a) - (b) =2,923.46)

The amount of estimated saving of S\$2,923.46 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust), MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA), AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.