

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20014299/KQD3E2

**Date:** 26/01/2021

### REFERENCE

Insured/Claimant: Pu Xiaojun Policy No: DMPCSNA00003832001

Date of Loss: 20/12/2020 Nature of Claim: OD

Claim No: SNM20D204957/C01/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **S5337CD**

Make & Model: MAZDA 3, 1.5 (A)

Reg. Date: 18/01/2017 (Man. Year: 2016)

Colour: Metallic Red

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: P520374125

Chassis No: JM6BM42A8G0345916

Odometer: 28510 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Front Left Side: Toyo 8 mm

Front Right Side: Toyo 8 mm

Rear Tyre Size: 205/60 R16

Rear Left Side: Toyo 8 mm

Rear Right Side: Toyo 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,055.00	2,419.00	636.00	20.82
Miscellaneous Items	140.00	90.00	50.00	35.71
Labour	243.60	243.60	0.00	0.00
Paintwork Labour	708.76	708.76	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,147.36</b>	<b>3,461.36</b>	<b>686.00</b>	<b>16.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,750.00</b>		
<b>- Excess (S\$)</b>	0.00	1,000.00	-1,000.00	
<b>(S\$)</b>	4,147.36	1,750.00	2,397.36	57.80
<b>+ GST 7.00/7.00% (S\$)</b>	290.32	122.50	167.82	57.81
<b>Nett Amount (S\$)</b>	<b>4,437.68</b>	<b>1,872.50</b>	<b>2,565.18</b>	<b>57.80</b>

### INSPECTION

Date of Assignment: 22/12/2020 Present Location:

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 23/12/2020 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Jan 2021)
<b>Parts:</b> 144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for S5337CD)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Parts		3,055.00 F	*2,419.00 F	
<b>Total Parts (S\$)</b>						<b>3,055.00</b>	<b>2,419.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	140.00	90.00
			<b>Sub Total (\$)</b>	<b>140.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	708.76	708.76
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	243.60	243.60
			<b>Gross Labour Cost (\$)</b>	<b>952.36</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >