

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/0989/2020/NS  
DATE : 18-Dec-20  
WIP : 63242

*Justin.*

*\$1952*

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.  
YOUR INSURED VEH NO : SHA 7366 Z

## First Capital Insurance Ltd

36 Robinson Road  
# 16-01 City House  
Singapore 068877

Attn: Motor Claims Dept  
Tel: 6854 3909 Fax: 6507 3849

OWNER'S NAME : MR RAJAN RAGHUPATHY  
ADDRESS : BLK 205 JURONG EAST STREET 21  
#02-157  
SINGAPORE 600205  
TELEPHONE : HP +65 90091672  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : DH0M120052832000  
VEHICLE NO : SLQ 1900 P  
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S  
MODEL YEAR : 29/6/2017  
ENGINE NO : CVN 039075  
CHASSIS NO : WAUZZZF48HA 165258  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 16-Dec-20  
PLACE OF ACCIDENT : ALONG BUKIT TIMAH



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLO 1900 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 700	
3	TO RESPRAY REAR BUMPER.	\$ 900.00 700	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S.N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 2,502.00</b>	





# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLO 1900 P

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>Repair</i>		\$	2,181.00	+
2	REAR BUMPER FIXING PARTS		\$	72.00	+
3	REAR BUMPER SECURING STRIP		\$	220.00	+
4	REAR BUMPER SPOILER		\$	246.00	+
5	REAR LIGHT REFLECTOR - RH REAR		\$	41.00	+
6	REAR BUMPER CARRIER		\$	886.00	+
7	REAR BUMPER CARRIER SEAL	2	\$	28.00	+
8	REAR BUMPER GUIDE SECTION - LH/RH	2	\$	44.00	+
9	REAR PARKING AID SENSOR - INNER/OUTER		\$	242.00	+
10	REAR PARKING AID SEAL RING	4	\$	14.00	+
11	SUNDRIES <i>Not new</i>		\$	200.00	+
<b>TOTAL SPARE PARTS</b>		:	\$	<b>4,174.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>2,502.00</b>	
<b>GRAND TOTAL</b>		:	\$	<b>6,676.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME : Adrian L.  
SURVEYED DATE : 23/12/20  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : XHP Authored, 03 Days  
HLS

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT