



Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Lump Sum	
ERV	23k.

TO: AXA
Vehicle No : SLC 4668 P
Make & Model : HONDA VEZEL
DATE:19/12/2020

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	HEAD LAMP <i>cracked RH</i>	2	\$ 1,890.00	\$ 3,780.00 1890
2	HEAD LAMP SIDE BRACKET <i>Neu</i>	2	\$ 75.40	\$ 150.80 X
3	HEAD LAMP LOWER HOLDER <i>Neu</i>	2	\$ 141.50	\$ 283.00 X
4	FRONT BUMPER <i>cracked</i>	1	\$ 489.80	\$ 489.80 ✓
5	FRONT BUMPER SIDE RETAINER <i>RH Dmgd</i>	2	\$ 85.00	\$ 170.00 35
6	FRONT BUMPER LOWER SIDE BRACKET <i>Neu</i>	2	\$ 75.00	\$ 150.00 X
7	FRONT BUMPER REINFORCEMENT <i>Neu</i>	1	\$ 625.40	\$ 625.40 X
8	FRONT BUMPER LOWER GRILLE <i>Neu</i>	1	\$ 321.00	\$ 321.00 X
9	FRONT BUMPER FOG LAMP RH <i>Neu</i>	1	\$ 398.00	\$ 398.00 X
10	FRONT BUMPER FOG LAMP COVER RH <i>lit</i>	1	\$ 161.00	\$ 161.00 ✓
11	FRONT BUMPER LOWER DIFFUSER <i>torn</i>	1	\$ 279.60	\$ 279.60 ✓
12	FRONT GRILLE <i>cracked</i>	1	\$ 375.40	\$ 375.40 ✓
13	FRONT GRILLE BADGE <i>Neu</i>	1	\$ 67.30	\$ 67.30 ✓
14	FRONT GRILLE OUTER PAD <i>Neu</i>	1	\$ 276.40	\$ 276.40 X
15	FRONT GRILLE CHROME MOULDING <i>Neu</i>	2	\$ 76.90	\$ 153.80 X
16	FRONT GRILLE TOP SUPPORTOR <i>Neu</i>	1	\$ 166.80	\$ 166.80 X
17	FRONT WIPER GARNISH <i>cracked</i>	1	\$ 677.50	\$ 677.50 X
18	FRONT WIPER GARNISH TOP RUBBER <i>Neu</i>	1	\$ 89.00	\$ 89.00 X
19	SUPPORT TOP GARNISH <i>Neu</i>	1	\$ 224.30	\$ 224.30 X
20	WIPER TANK <i>cracked</i>	1	\$ 117.90	\$ 117.90 ✓
21	HORN <i>Neu</i>	1	\$ 350.00	\$ 350.00 X
22	FRONT FENDER RH <i>Dented</i>	1	\$ 653.30	\$ 653.30 ✓
23	FRONT FENDER INNER SHIELD RH <i>torn</i>	1	\$ 186.50	\$ 186.50 ✓
24	FRONT FENDER INNER SIDE GARNISH RH <i>Neu</i>	1	\$ 132.30	\$ 132.30 X
25	FRONT FENDER ARCH GARNISH RH <i>lit</i>	1	\$ 389.70	\$ 389.70 ✓
26	FRONT EXTENTION PANEL RH (OUTER) <i>Dented</i>	1	\$ 475.60	\$ 475.60 ✓

27	FRONT EXTENTION PANEL RH (INNER) <i>Repair</i>	1	\$	455.80	\$ x 455.80
28	FRONT EXTENTION PANEL BRACKET RH <i>Repair</i>	1	\$	255.30	\$ x 255.30
29	FRONT ABSORBER RH	1	\$	530.10	\$ x 530.10
30	FRONT LOWER ARM RH	1	\$	450.00	\$ x 450.00
31	FRONT KNUCKLE ARM RH	1	\$	349.70	\$ x 349.70
32	FRONT WHEEL BEARING RH	1	\$	190.10	\$ x 190.10
33	FRONT DRIVE SHAFT RH	1	\$	1,107.00	\$ x 1,107.00
34	STEERING RACK AND PINION	1	\$	1,192.40	\$ x 1,192.40
35	FROTN ORIGINAL RIM <i>ut</i>	1	\$	890.00	\$ 580 890.00
36	FRONT DOOR RH <i>Repair</i>	1	\$	989.70	\$ x 989.70
37	FRONT DOOR SIDE MIRROR RH <i>Not New</i>	1	\$	894.40	\$ x 894.40
38	FRONT DOOR OUTER MOULDING RH <i>new</i>	1	\$	172.10	\$ x 172.10
39	FRONT DOOR WEATHERSTRIP RH <i>new</i>	1	\$	189.30	\$ x 189.30
40	FRONT SIDE SKIRT RH <i>new</i>	1	\$	978.50	\$ x 978.50

5200.40
4160.32 S.N. 580

Subtotal : \$ 19,788.80

Less 20% \$ 3,957.76

Parts Total : \$ 15,831.04

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT FENDER INNER SHIELD CLIP SET <i>new</i>	1	\$ 40.00	\$ 30 40.00
2	FRONT FENDER INNER SIDE GARNISH CLIP <i>new</i>	1	\$ 30.00	\$ x 30.00
3	FRONT WIPER GARNISH CLIP SET <i>new</i>	1	\$ 40.00	\$ 30 40.00
4	HEAD LAMP BULK SET <i>new</i>	1	\$ 80.00	\$ x 80.00
5	FRONT GRILLE CLIP SET <i>new</i>	1	\$ 40.00	\$ 20 40.00
6	FRONT BUMPER CLIP SET <i>new</i>	1	\$ 50.00	\$ 30 50.00
7	FRONT EXTENTION PANEL RH SEALANT <i>new</i>	1	\$ 80.00	\$ 40 80.00
8	FRONT EXTENTION PANEL RH SEALANT <i>new</i>	1	\$ 80.00	\$ x 80.00
9	FRONT EXTENTION PANEL BRACKET SEALANT <i>new</i>	1	\$ 80.00	\$ x 80.00
10	FRONT TYRE <i>new</i>	1	\$ 400.00	\$ x 400.00
11	FRONT SIDE SKIRT CLIP SET <i>new</i>	1	\$ 90.00	\$ x 90.00
				\$ 1,010.00

LABOUR			PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	700	\$	1,600.00
TO SPRAY PAINT AFFECTED AREA	750	\$	1,500.00
TO PERFORM LIGHTING & WIRING CHECK	30	\$	100.00

