



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

25/02/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 111

Xiao Tong.

Accident date:

Estimated repair cost for vehicle no: SMR592J KIA CERATO 1.6 19'

CHASSIS: KNAF5416MK5050808

S/n	Qty	Items	U/price	Amount
1	1	Rear R/H Door <i>Peris</i>		\$558.61 <i>x</i>
2	2	Rear R/H Door Hinge <i>Men</i>	\$263.20	\$526.40 <i>x</i>
3	1	Rear R/H Door Outer Handle <i>3ml</i>		\$51.88 <i>x</i>
4	1	Rear R/H Door Outer Handle (Small) <i>3ml</i>		\$22.90 <i>x</i>
5	2	Rear R/H Door Frame Sticker <i>2</i>	\$35.00	\$70.00 <i>+</i>
6	1	Rear R/H Door Inner Rubber <i>3ml</i>		\$91.20 <i>+</i>
7	1	Rear R/H Door Inner Trimboard <i>3ml</i>		\$514.50 <i>+</i>
8	8	Rear R/H Door Inner Trimboard Clip	\$6.50	\$52.00 <i>x</i>
9	1	Rear R/H Door Lock <i>Men</i>		\$284.60 <i>+</i>
10	1	Rear R/H Door Window Regulator Motor Assy <i>Men</i>		\$276.50 <i>+</i>
11	1	Rear R/H Fender <i>Dented</i>		\$1,349.63 <i>✓</i>
12	1	Rear R/H Fender Cowling <i>2ml</i>		\$165.00 <i>+</i>
13	10	Rear R/H Fender Cowling Clip <i>3ml</i>	\$6.50	\$65.00 <i>+</i>
14	1	R/H Side Skirt <i>Dented</i>		\$546.50 <i>✓</i>
15	1	Rear R/H Rim <i>At</i>		\$926.16 <i>4w/pw</i>
16	1	Rear R/H Tyre <i>4w/pw</i>		\$350.00 <i>x</i>

189613 S.N: 400

170651

Subtotal :- \$5,850.88

Labour charges

To check wheel alignment computer

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 60

Towing fee

\$150.00 X.

Panel beating

\$1,800.00 ~~500.~~

Spray painting

\$1,600.00 ~~800.~~

Subtotal :- \$3,800.00

Total:- \$9,650.88

Supplementary: 946.76

total: 4523.27

1/s: 3.6k.

05 Days.

3.6k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

25/02/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date:

Supplementary repair cost for vehicle no: SMR592J KIA CERATO 1.6 19'

CHASSIS: KNAF5416MK5050808

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper <i>Defound.</i>		\$786.65 <i>576.40</i>
2	1	Rear Bumper R/H Side Retainer <i>new</i>		\$35.00 ✓
2	1	Rear Windscreen Moulding <i>new</i>		\$185.00 ✓

Subtotal :- \$1,006.65

Labour charges

To remove & refit cushion

796.40
716.76
~~\$280.00~~ *60.*

To remove & refit rear windscreen

\$120.00 ✓

Gum

230
~~\$50.00~~

Subtotal :- \$450.00

Total:- \$1,456.65

Supplementary: 946.76