

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44

Premier @ Kaki Bukit (Gate 1)

Singapore 415875

Tel: 63441918

Date : 21/12/2020

Vehicle : SBP8138B

Make/Model : Toyota Alphard 2.5S

ORD : 2015

Chassis : AGH300013034

ODO : 236283

ACC Date : 19/12/2020

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way, #09-16 AIG Building

Singapore 079120

*Susper.***ESTIMATE**

S/N	Qty	Description & Specification	Amount S\$
List Items			
1	1	Tailgate <i>Dented</i>	\$3,078.50 1718
2	1	Tailgate 'ALPHARD' emblem <i>New</i>	\$96.40 ✓
3	1	Tailgate lock w/auto motor <i>Dented</i>	\$415.80 ✓
4	1	Tailgate w/stripe <i>at</i>	\$335.20 ✓
5	1	Tailgate inner trim board <i>Behind</i>	\$610.80 526
6	1	Tailgate absorber LH	\$263.70 X
7	1	Tailgate absorber RH <i>} not new</i>	\$263.70 X
8	1	Rear w/screen moulding top	\$109.20 ✓ 58
9	1	Rear w/screen moulding bottom <i>} New</i>	\$104.80 58
10	1	Rear w/screen moulding LH	\$98.30 45
11	1	Rear w/screen moulding RH	\$98.30 45
12	1	Rear bumper <i>Behind</i>	\$1,146.80 ✓
13	1	Rear bumper tow cover <i>Behind</i>	\$60.40 ✓
14	1	Rear bumper side retainer LH	\$77.10 ✓
15	1	Rear bumper side retainer RH <i>} New</i>	\$77.10 ✓
16	1	Rear bumper bracket LH <i>} New</i>	\$81.80 X
17	1	Rear bumper bracket RH <i>} New</i>	\$81.80 X
18	1	Rear bumper reverse sensor inner LH <i>Dented</i>	\$272.60 ✓
19	1	Rear bumper reverse sensor outer LH <i>New</i>	\$272.60 X
20	1	Rear end panel <i>Dented</i>	\$745.20 ✓
21	1	Rear end panel top garnish <i>Behind</i>	\$259.80 ✓
			Less 25%
			\$2,137.48
			List Total
			\$6,412.42
S/Nett Items			
1	1set	Tailgate inner trim board clips <i>New</i>	\$100.00 30
2	1set	Rear w/screen sealant <i>} New</i>	\$60.00 40
3	1set	Rear w/screen inner seal	\$40.00 30
4	1set	Rear bumper clips <i>New</i>	\$100.00 30
5	1set	Rear bumper reverse sensor o-ring <i>New</i>	\$40.00 ✓
6	1set	Rear end panel sealant <i>New</i>	\$60.00 ✓
7	1set	Rear end panel top garnish clips <i>New</i>	\$40.00 20
			S/Nett Total
			\$440.00

5936.40

A452.30

250

<u>Labour</u>			
1	To cut, weld rear end panel, to replace tailgate assy, to repair rear floor panel and re-align on all accident affected areas	\$1,400.00	800
2	To putty and respray on rear accident portion	\$1,000.00	800
3	To check rear lighting and wiring	\$100.00	30
4	To apply anti-rust corrosion on rear affected areas	\$100.00	60
5	To remove and refit rear w/screen	\$200.00	120
6	To transfer tailgate mechanism to new tailgate	\$300.00	80
7	To remove and refit rear garnish, upholstery etc to assist repair	\$200.00	60
		Labour Total	\$3,300.00
		Grand Total	\$10,152.42
Trident Auto Service Centre Pte Ltd			

1850

Supplementary : 400

total : 7052.30

h/s: 5.8K

06 Days.

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44

Premier @ Kaki Bukit (Gate 1)

Singapore 415875

Tel: 63441918

Date : 21/12/2020

Vehicle : SBP8138B

Make/Model : Toyota Alphard 2.5S

ORD : 2015

Chassis : AGH300013034

ODO : 236283

ACC Date : 19/12/2020

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way, #09-16 AIG Building

Singapore 079120

Supplementary

S/N	Qty	Description & Specification	Amount S\$
S/Nett Items			
1	1	Reverse camera <i>Damaged</i>	\$400.00 ✓
S/Nett Total			\$400.00

Trident Auto Service Centre Pte Ltd

Supplementary : 400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: