



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Mr Lee Poh Kwang Blk 77 Bedok North Rd #06-216 Singapore 460077 Contact No Mobile: 98373473		Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/Mr Lee Poh Kwang SLV9903C / 25/01/201 / 0 MMBSTA13AJH000725 3A92UGN1645 MIT/18MY ATTRAGE 1.2 CVT W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	19/12/2020/ 11:20	QUE	261 / Edwin Caina	60959
Description of Goods / Services					
					Qty Unit Price Disc% Amount
E PNT88000 RENEW RR BUMPER REPAIR RR END PNL					640 2240.00
E PNT98000 RESpray RR BUMPER & RR END PNL					550 1100.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET					X 320.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM					50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					280.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR					100.00
M SUNDRY SUPPLY REVERSE SENSOR					1 280.00
M SUNDRY Sundries					20 50.00
M FACE, RR BUMPER					1.00 748.00 00.00 748.00
M CLIP, RR BUMPER					4.00 4.00 00.00 16.00
M BRACKET, RR BUMPER, LH					1.00 28.00 00.00 28.00
M BRACKET, RR BUMPER, RH					1.00 28.00 00.00 28.00

SURVEYOR NAME: Sten (LKK) 5/1/21, 11-00am
SURVEYOR SIGNATURE: Wil M
DATE: 3 days
REMARKS: PIP

Confirm & accepted by
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
Authorized signatory and company stamp

Nett 5,240.00
7% GST on 5240.00 366.80
Total Payable 5,606.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.