

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0998/2020/NS
DATE : 22-Dec-20
WIP : 63656

VEHICLE IS NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR THAM TIEN HOONG FIDELIS
ADDRESS : BLK 165 BISHAN STREET 13
#19-274
SINGAPORE 570165
TELEPHONE : HP +65 97703227
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100454499-04
VEHICLE NO : **SJZ 1406 B**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 29/2/2016
ENGINE NO : CVN 002251
CHASSIS NO : WAUZZZF48GA024009
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Dec-20
PLACE OF ACCIDENT : ORCHARD REDEZVOUS HOTEL CARPARK



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 1406 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	1100
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,282.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 1406 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Repis</i>		\$ 2,111.00	X
2 FRONT BUMPER FIXING PARTS <i>neu</i>		\$ 282.00	X
3 FRONT BUMPER SECURING STRIP <i>neu</i>	2	\$ 70.00	X
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not per</i>		\$ 208.00	X
5 FRONT BUMPER AIR GUIDE - RH		\$ 62.00	X
6 FRON TBUMPER AIR GUIDE GRILLE - RH <i>HP</i>		\$ 361.00	X
7 FRONT BUMPER GUIDE SECTION - RH <i>HP</i>		\$ 37.00	X
8 FRONT FENDER - RH <i>Defted</i>		\$ 758.00	✓
9 FRONT FENDER ATTACHMENT PARTS <i>neu</i>		\$ 200.00	+
10 FRONT FENDER CLOSING ELEMENT - RH <i>Not per</i>		\$ 49.00	+
11 FRONT FENDER BRACKET - RH <i>?</i>		\$ 35.00	?
12 DEFORMATION ELEMENT BRACKET - RH <i>neu</i>		\$ 49.00	X
13 FRONT FENDER BRACE - RH <i>?</i>		\$ 117.00	?
14 WHEEL HOUSING LINER - RH <i>Not per</i>		\$ 239.00	+
15 WHEEL HOUSING LINER ATTACHMENT PARTS <i>HP</i>		\$ 90.00	+
16 WHEEL SPOILER <i>HP</i>		\$ 73.00	+
17 WHEEL SPOILER TRIM <i>HP</i>		\$ 36.00	+
18 STONE CHIP GUARD <i>HP</i>		\$ 50.00	X
19 TOP FENDER LEDGE COVER - UPPER <i>HP?</i>		\$ 31.00	?
20 TOP FENDER LEDGE COVER - LOWER <i>HP?</i>		\$ 23.00	?
SUB-TOTAL SPARE PARTS	:	\$ 4,881.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 1406 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 LED HEADLIGHT - RH <i>ct</i>		\$ 7,693.00	✓
22 LIFT CYLINDER - RH <i>pcu</i>		\$ 208.00	+
23 FRONT ALUMINIUM RIM - RH <i>Abel a</i>		\$ 589.00	+
24 SUNDRIES ?		\$ 200.00	?
TOTAL SPARE PARTS	:	\$ 13,571.00	
TOTAL LABOUR CHARGES	:	\$ 5,282.00	
GRAND TOTAL	:	\$ 18,853.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lij
SURVEYED DATE : 23/02/201
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT